

Mr Cyril Brown
13 Valetta Road
London
W
London
W3 7TQ

Date: 23/02/2026
Our Ref: 00030782/HASSANA
Your Ref: EHR96676

To the Court REPAIRABLE REPORT

Dear Sirs,
Client: **Mr Cyril Brown**

We refer to your instructions received on **18 February 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: LAND ROVER RANGE ROVER AUTOBIO		Colour: BLACK	Speedo: 36035 Miles	
Reg No: KM73ZTL	Registered: Nov 2023	Type: Estate	Trans: Automatic	
Vin No: SALKA9AW1RA202780	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno	
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manfd: 2023			
Brakes: Not Known	Tax Exp:			Spare Tyre Not Known
Steering: Not Known	Fuel: Diesel			Centre Belt Not Tested
Extras: Not Seen	C.C.: 2997			L/H/F Belt Not Tested
Air Bags Deployed: Not Known	BHP: 345.	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno	
Damage: Moderate Collision/Impact LH Front Mirror		Incident: 23/01/2026		

Vehicle Value: **£88,000.00** Repair Cost: **£3,202.22 inc VAT** (3.64% of PAV) Roadworthy: **Yes**

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the left hand front mirror.

VEHICLE HISTORY CHECK

23/02/2026 - According to the Experian database; there is a plate change on record

REPAIR SCHEDULE

New parts required:-Front Door Window Outer Channel Strip (L), Front Door Ext Mirror (Elec/Htd/Retr) (L), Front Door Exterior Mirror Cover (L), F. Door Exterior Mirror Adjusting Motor (L), Ext Mirror Glass (Elec/Htd/Auto Dim) (L), Exterior Mirror Side Repeater Lamp (L), Exterior Mirror Camera (L), Water Wading Assistant Sensor (L)

Repaint only parts:-Front Door Exterior Mirror Cover (L), Colour mixing (1), Sample colour creation (1)

Specialist/Sundry charges:-Car Kit, Compilation assesment by repairer, Epa, Final Inspection & Road Test, pre-repair clean, standard vehicle shutdown, system diagnostic post check, system diagnostic pre check, Wash/Clean

Remove And Refit parts:-Front Door Centre Moulding (L), Front Door Lower Cover (L), Front Door Outer Handle Cover (L)



COST OF REPAIRS

An Glass's Repair Estimate estimate has been obtained from General Auto Care, 1070-1072 Harrow Rd London, NW, + (Tel. 020 8969 6189) in the sum of £715.00 labour plus parts at manufacturer's list prices plus £37.06 for paint and materials plus £218.60 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be low and we have agreed an amended labour figure of £770.38 The labour charge is based on 6.5 hours at a rate of £118.52 per hour. We have also agreed that the cost of paint and materials will be limited to £37.06. The cost of the necessary replacement parts will be approximately £1,642.48, the specialist/sundry charges will be £218.60, the VAT liability on this repair will amount to some £533.70 giving a total repair cost of £3,202.22 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 28/11/2023. The corresponding CAP Guide (model code: 98765) adjusted retail value for vehicles of this type and age in the January 2026 guide is £88,000.00 at 36035 Miles, trade value is £81,300.00 and mid value is £84,650.00. We place the pre-accident value of this particular vehicle at £88,000.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £3,225.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 23rd February 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 2 to 3 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE


In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions (ACHL) commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Hassan Anwar ATA VDA
Exclusive Vehicle Assessors