

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

Mr M Dore
3 The Grove,
Chorley
PR7 1PU


Date: 24/03/2026
Our Ref: 00077428/PK
Your Ref: EHR97441

Engineer Repairable Report

Dear Sirs,

Client/Insured: **Mr M Dore**

We refer to your instructions received on **27 February 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: FORD FIESTA TITANIUM TURBO MHEV	Colour: BLUE	Speedo: 50021	Miles
Reg No: PK70GVV	Registered: Sep 2020	Type: 5 Door Hatchback	Trans: Manual
Vin No: WF0JXXGAHJLE27479	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manf'd: 2020		Spare Tyre Not Know
Brakes: Not Known	Tax Exp:		Centre Belt Not Tested
Steering: Not Known	Fuel: Petrol		
Extras: Not Seen	C.C.: 999		
Air Bags Deployed: Not Known	BHP: 123.	L/H/F Belt Not Tested	L/H/R Belt Not Tested
Damage: Light Accidental Damage RH Side Bumper	Incident: 26/02/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £8,941.00		Repair Cost: £4,285.07 inc VAT	(47.93% of PAV) Roadworthy: Yes

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light accidental damage to the right hand side bumper, to the quarter panel, and to the door

VEHICLE HISTORY CHECK

27/02/2026 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-R/Sill Foil, R/R S-Window Glue, Panel Sundries, Decals O/S

Repairable parts:-Repair R/R Door, Repair R/R Side Panel

Repaint only parts:-R/Door Lower Repair Painting <50%, R/R Door Repair Painting <50%, Rear Bumper Repair Paint Plastic, R/R Side Panel Repair Painting <50%, R/Outer Sill Panel Surface Paint, R/Upper A-Pillar Surface Paint, R/Roof Frame Surface Paint, Machine Polish X4, Sill Dressing O/S Surface Paint, Roof Section Detail Mask, Lamp Panel Detail Mask, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Tech Data + Methods, E.P.A. Charge, Car Care Kit, Sundry Part

Remove And Refit parts:-Add/Time For One Main Position, Right Front Door, R/F Door Trim, Right Front Outer Door Handle, R/F Outer Door Channel Moulding, R/Outer Mirror, R/R Outer Door Handle, R/Rear Door Window Seal, Rear Bumper Air Deflector, Rear Bumper, L/R Reflector, Right Rear Fog lamp, Adhere R/Door Sill Foil, R/Side Panel Window, Right Rear Wheelhouse Shell, Right Rear Wheel

Parts to check:-Check Remove Decals, Check Pre Wash, Check Wash/Vacuum, Check QC / Road Test, Check Vehicle Diag Pre Check, Check Vehicle Diag Post Check

COST OF REPAIRS

The repairers, Rightway Paint and Body, WN35BD, have compiled an estimate in the sum of £2,681.00 plus parts at manufacturer's list prices plus £1,036.00 for paint and materials plus £90.00 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be high and we have agreed a reduction with the repairers of £332.50 to £2,348.50 in their final account. The labour charge is based on 28.2 hours at a rate of £83.28 per hour. We have also agreed that the cost of paint and materials will be limited to £1,036.32. The cost of the necessary replacement parts will be approximately £96.07, the specialist/sundry charges will be £90.00, the VAT liability on this repair will amount to some £714.18 giving a total repair cost of £4,285.07 including VAT **subject to any undisclosed damage. We are pleased to confirm that we have achieved total gross savings in this matter of £399.00.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 24/09/2020. The corresponding Glass's Guide (model code: 321931001) adjusted retail value for vehicles of this type and age in the February 2026 guide is £8,941.00 at 50021 Miles, trade value is £6,866.00 and mid value is £7,903.50. We place the pre-accident value of this particular vehicle at £8,941.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £4,300.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 24th March 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 9 to 10 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it un roadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Exclusive Repair Network commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Phil Kendrick AQP CAE AMIMI
Connexus Vehicle Assessors