

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

2/2

Mr Owen Morris
2 Newby Close
Bedlington
Northumberland
NE22 5YT

Date: 27/04/2026
Our Ref: 00078892/PK
Your Ref: 573250

Engineer Repairable Report - Amended Report

Dear Sirs,

Client/Insured: **Mr Owen Morris**

We refer to your instructions received on **22 April 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: AUDI A3 S LINE 35 TFSI	Colour: GREY	Speedo: 18356	Miles	
Reg No: NJ73JFZ	Registered: Sep 2023	Type: 5 Door Hatchback	Trans: Manual	
Vin No: WAUZZZGY2RA011275	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno	
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manf'd: 2023			
Brakes: Not Known	Tax Exp:			Spare Tyre Not Know
Steering: Not Known	Fuel: Petrol			Centre Belt Not Tested
Extras: Not Seen	C.C.: 1498	L/H/F Belt Not Tested	L/H/R Belt Not Tested	
Air Bags Deployed: Not Known	BHP: 147.	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno	
Damage: Light Accidental Damage Rear Bumper	Incident: 17/03/2026			
Vehicle Value: £21,532.00		Repair Cost: £2,108.75 inc VAT	(9.79% of PAV) Roadworthy: Yes	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light accidental damage to the rear bumper.

ENGINEER'S COMMENTS

15/05/2026 - Final costs

VEHICLE HISTORY CHECK

22/04/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rear Cover Bumper, Rear Bumper Spoiler, Bolts As Per Methods

Repair only parts:-Rear Cover Bumper New Part Paint K1r, Polish To Finish, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Car Care Kit, Bs10125 Charge, Epa Charge, Estimate Compilation, Vm Approval Fee, Sundry Part

Remove And Refit parts:-Gfs Controlled Function, Rear Bumper Cover, Renew Rear Bumper Cover, Renew Rear Lower Bumper Spoiler, Specialist Clean & Valet

Parts to check:-Check Final Qc, Check Veh Diag Pre Check, Check Veh Diag Post Check

COST OF REPAIRS

The repairers, Lookers Paint & Body Centre NE, Unit A2 First Avenue, Tyne Tunnel Estate, North Shields, NE29 7SU (Tel. 0191 2729100), have compiled an estimate in the sum of £811.20 plus parts at manufacturer's list prices plus £427.48 for paint and materials plus £284.73 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be high and we have agreed a reduction with the repairers of £144.96 to £666.24 in their final account. The labour charge is based on 8 hours at a rate of £83.28 per hour. We have also agreed that the cost of paint and materials will be limited to £427.48. The cost of the necessary replacement parts will be approximately £551.00, the specialist/sundry charges will be £112.57, the VAT liability on this repair will amount to some £351.46 giving a total repair cost of £2,108.75 including VAT **subject to any undisclosed damage. We are pleased to confirm that we have achieved total gross savings in this matter of £380.54.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 17/09/2023. The corresponding Guide (model code: 18700) adjusted retail value for vehicles of this type and age in the March 2026 guide is £21,532.00 . We place the pre-accident value of this particular vehicle at £21,532.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £2,125.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 27th April 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.** We understand that the vehicle is still being used by the owner.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



. AQP CAE AMIMI
Connexus Vehicle Assessors