

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

Mr Mark Dennis
10 Heatherstone Road
Worthing
West Sussex
BN11 2HF


Date: 13/05/2026
Our Ref: 00079300/PK
Your Ref: 575669 \ P76668434-1

Engineer Repairable Report

Dear Sirs,

Client/Insured: **Mr Mark Dennis**

We refer to your instructions received on **06 May 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: SKODA OCTAVIA SE TECHNOLOGY TSI	Colour: BLUE	Speedo: 3968	Miles
Reg No: BL25OXF	Registered: Jun 2025	Type: 5 Door Estate	Trans: Manual
Vin No: TMBKA8NX7SY130601	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manf'd: 2025		
Brakes: Not Known	Tax Exp:		
Steering: Not Known	Fuel: Petrol		
Extras: Not Seen	C.C.: 1498	Spare Tyre Not Know	
Air Bags Deployed: Not Known	BHP: 114	Centre Belt Not Tested	
Damage: Light Accidental Damage LH Rear Bumper	Incident: 01/05/2026	L/H/F Belt Not Tested	L/H/R Belt Not Tested
		L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £21,532.00		Repair Cost: £1,338.49 inc VAT	(6.22% of PAV)
		Roadworthy: Yes	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light accidental damage to the left hand rear bumper.

VEHICLE HISTORY CHECK

06/05/2026 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Car Care Kit

Repairable parts:-Repair Rear Cover Bumper

Repaint only parts:-Rear Cover Bumper Repair Paint Plastic, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-E.P.A. Charge, Data Research, Pre Repair Diag, Post Repair Diag

Remove And Refit parts:-Rear Bumper Cover, Rear Reflector, Release Bumper Corner, Detail Mask Rear Lamp, Post Bodywork Clean Car

Parts to check:-Check And Quality Control

COST OF REPAIRS

The repairers, Harwoods ARC Five Oaks, Horesham Road, Five Oaks, Five Oaks, RH14 9AZ (Tel. 01403 787 000),

have compiled an estimate in the sum of £504.00 plus parts at manufacturer's list prices plus £468.41 for paint and materials plus £133.00 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 7.2 hours at a rate of £70.00 per hour. We have also agreed that the cost of paint and materials will be limited to £468.41. The cost of the necessary replacement parts will be approximately £10.00, the specialist/sundry charges will be £133.00, the VAT liability on this repair will amount to some £223.08 giving a total repair cost of £1,338.49 including VAT **subject to any undisclosed damage. We are pleased to confirm that we have achieved total gross savings in this matter of £13.86.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 24/06/2025. The corresponding CAP Guide retail value for vehicles of this type and age in the May 2026 guide is £21,352.00 at 3968 Miles, trade value is £19,800.00 and mid value is £20,576.00. We place the pre-accident value of this particular vehicle at £21,532.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £1,350.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 13th May 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it un roadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.** We understand that the vehicle is still being used by the owner.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



. AQP CAE AMIMI
Connexus Vehicle Assessors