


Mr Saji Gopalan
257 Ripon Road
Stevenage
Stevenage
SG1 4LR

Date: 18/11/2025
Our Ref: 00023439/DME
Your Ref: EHR91038

To the Court
REPAIRABLE REPORT - Amended Report

Dear Sirs,
Client: **Mr Saji Gopalan**

We refer to your instructions received on **28 October 2025** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle:	VOLVO XC60 + B4 MHEV AUTO		Colour:	WHITE	Speedo:	24069	Miles
Reg No:	NV23DPZ	Registered:	Mar 2023	Type:	Estate	Trans:	Automatic
Vin No:	LYVUZK9V5PB317576	MOT Exp:		R/H/F Tyre	Not Kno	R/H/R Tyre	Not Kno
Mods:	Not Seen	Cond:	Good	R/H/F Belt	Not Tested	R/H/R Belt	Not Tested
Audio:	Not Seen	Manfd:	2023			Spare Tyre	
Brakes:	Not Known	Tax Exp:				Not Known	
Steering:	Not Known	Fuel:				Centre Belt	
Extras:	Not Seen	C.C.:	1969			Not Tested	
Air Bags Deployed:	Not Known	BHP:	194.	L/H/F Belt	Not Tested	L/H/R Belt	Not Tested
Damage:	Light to Moderate Collision/Impact RH Rear	Incident:	27/10/2025	L/H/F Tyre	Not Kno	L/H/R Tyre	Not Kno
Vehicle Value: £33,130.00		Repair Cost: £6,097.81 inc VAT		(18.41% of PAV)		Roadworthy: No	

AMENDED REPORT----- 18/11/2025 ---- SUPPLEMENTARY COSTS.

Please note the repairers have updated the repair method and parts costs with supporting images.

Authority sent via Audatex.

=====

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF DAMAGE

The vehicle has suffered light to moderate collision impact to the right hand rear.

VEHICLE HISTORY CHECK

31/10/2025 - According to the Experian database; there is a plate change on record



REPAIR SCHEDULE

New parts required:-Rear Bumper, Rr Bumper Prot Mldg, L/R Bumper Cover, R/R Bumper Cover, Tailgate Lwr Sensor, Tailgate Opening Sen, R/R Out Parking Sensor, R/R Out Sensor Suspension, Badge Model, Engine Badge, Sundries

Repairable parts:-Repair Methods, Repair Rear Panel

Repaint only parts:-Rear Bumper Spoiler New Part Paint K1r, R/R Out Parking Sensor new Part Paint K1r, Rear Spoiler Cover Repair Paint Plastic, Rear Panel Repair Painting <50%, Lower Tailgate Repair Painting <50%, Two Colour Paint Allowance, De-Nib And Polish Surface Paint, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Bs10125 Charge, Car Care Kit, E.P.A. Charge, Energy Cost, Pas 2060 Charge, Post Repair Sweep, Pre Repair Sweep, Repair Methods, Anti-Corrosion

Remove And Refit parts:-Tailgate Trim, Renew Badge, L/R Interior Lamp, R/R Interior Lamp, Renew Rear Bumper, Allowance EV/Hybrid Power Down, Allowance Identify Adas Fee, Inc Sanitise Pre Repair Clean, Allowance R/Test & Final QC, Allowance Wash And Vac, Corrosion Protection 1St Panel

Parts to check:-Check Wiring Set, Check Rear Bumper Support, Check Rear Bumper Fixed

COST OF REPAIRS

The repairers, Cougar Accident Repair Centre Limited (Tel. 01582 411120), have compiled an estimate in the sum of £2,088.90 plus parts at manufacturer's list prices plus £874.52 for paint and materials plus £347.00 for specialist/sundry charges. Having calculated the time involved in this repair I consider this to be reasonable. The labour charge is based on 21.1 hours at a rate of £99.00 per hour. I have also agreed that the cost of paint and materials will be limited to £874.52. The cost of the necessary replacement parts will be approximately £1,771.09, the specialist/sundry charges will be £347.00, the VAT liability on this repair will amount to some £1,016.30 giving a total repair cost of £6,097.81 including VAT **subject to any undisclosed damage.**

REPAIRER VAT STATUS

I am informed that the repairer is registered for VAT

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to me the vehicle was first registered in 31/03/2023.

The corresponding Glass's Guide (model code: JGRF) adjusted retail value for vehicles of this type and age in the October 2025 guide is £33,130.00 at 24069 Miles, trade value is £29,900.00.

I place the pre-accident value of this particular vehicle at £33,130.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

I do not consider that any betterment contribution is required on this occasion.

RESERVE

I consider that a repair reserve of £6,100.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

I am pleased to confirm that I have authorised the repairers to proceed with the work via Audatex in accordance with your instructions, on the 3rd November 2025, on your behalf.

REPAIR DURATION

I consider that this repair will take some 6 to 7 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In my opinion this vehicle was not roadworthy at the time of my inspection as a result of the damage sustained due to Rear bumper compromised.

TEMPORARY REPAIRS

I suggest that it would not be practical to consider cost effective temporary repairs on this occasion to make this vehicle roadworthy.

For & on behalf of

A handwritten signature in black ink that reads "TIM CLARKE". The signature is written in a cursive, slightly slanted style.

Tim Clarke IMI VDA Accreditation, C.A.E., M.I.M.I.
Exclusive Vehicle Assessors