

Mr Chris Huxtable
33 Waterbeach Road
Dagenham
RM
DAGENHAM
RM9 4AB


Date: 27/05/2026
Our Ref: 00035503/HASSANA
Your Ref: EHR100984 \ GDMSA03058902

To the Court
REPAIRABLE REPORT - Supplementary Report

Dear Sirs,
Client: **Mr Chris Huxtable**

We refer to your instructions received on **01 May 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle:	AUDI S5 TFSI QUATTRO AUTO		Colour:	BLUE	Speedo:	90514	Miles
Reg No:	WA18UNH	Registered:	Mar 2018	Type:	Convertible	Trans:	Automatic
Vin No:	WAUZZZF52JN014116	MOT Exp:		R/H/F Tyre	Not Kno	R/H/R Tyre	Not Kno
Mods:	Not Seen	Cond:	Good	R/H/F Belt	Not Tested	R/H/R Belt	Not Tested
Audio:	Not Seen	Manfd:	2018			Spare Tyre	
Brakes:	Not Known	Tax Exp:				Not Know	
Steering:	Not Known	Fuel:	Petrol			Centre Belt	
Extras:	Not Seen	C.C.:	2995			Not Tested	
Air Bags Deployed:	Not Known	BHP:	349	L/H/F Belt	Not Tested	L/H/R Belt	Not Tested
Damage:	Moderate Collision/Impact LH Rear	Incident:	30/04/2026	L/H/F Tyre	Not Kno	L/H/R Tyre	Not Kno



Vehicle Value:	£17,627.00	Repair Cost:	£6,006.05 inc VAT	(34.07% of PAV)	Roadworthy:	No
----------------	-------------------	--------------	--------------------------	-----------------	-------------	-----------

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate collision/impact damage to the left hand rear.

VEHICLE HISTORY CHECK

06/05/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rear Bumper, Rear Bumper Spoiler, Rr Bumper Ctr Cover, Rr Bumper Ctr Cover, L/R Badge, Rear Badge Audi, Filler Lid Attachm, Car Care Kit, Sundry Parts

Repaint only parts:-Rear Bumper New Part Paint K1r, R/R Side Panel Repair Painting <50%, De Nib & Polish. Per Panel, Preparation For Pre-Painting

Specialist/Sundry charges:-Bsi Compliance, Epa, Methods Research Specialist

Blend only parts:-Bootlid Surface Paint, L/R Side Panel Surface Paint, Fuel Filler Flap Surface Paint Plast.

Remove And Refit parts:-Description, Gfs / Guided Function, Rear Wheel (Wheels), L/Side Window Moulding,

R/Side Window Moulding, Renew Rear Badge/Type Badge, Bootlid Trim, Boot Lid Handle, Inner Tail Lamps, Rear Bumper Cover, Renew Rear Bumper Cover, L/R Wheelhouse Shell, Rear Centre Bumper Cover, R/R Wheelhouse Shell, Fuel Flap, Rear Seat Cushion, L/R Side Pad, Right Rear Side Padding, Left Inner Sill Trim, Right Inner Sill Trim, L/Side Trim (Rear Seat Cushion And, R/Side Trim (Rear Seat Cushion And

Parts to check:-Rear Bumper Support, L/R Silencer, Adas Exploration, Qc & Road Test, Pre Rep Diag Scan, Post Rep Diag Scan, Wash And Vacuum, Est Pre Wash

COST OF REPAIRS

The repairers, South East Automotive Ltd (Tel. 02089840022), have compiled an estimate in the sum of £2,346.70 plus parts at manufacturer's list prices plus £1,293.28 for paint and materials plus £117.87 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 19.8 hours at a rate of £118.52 per hour. We have also agreed that the cost of paint and materials will be limited to £1,293.28. The cost of the necessary replacement parts will be approximately £1,247.19, the specialist/sundry charges will be £117.87, the VAT liability on this repair will amount to some £1,001.01 giving a total repair cost of £6,006.05 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 27/03/2018. The corresponding Cazana Guide (model code: 402088) adjusted retail value for vehicles of this type and age in the April 2026 guide is £17,627.00 at 90514 Miles, trade value is £14,983.00 and mid value is £16,305.00. We place the pre-accident value of this particular vehicle at £17,627.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £6,025.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 6th May 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 5 to 6 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE


In our opinion this vehicle was not roadworthy at the time of our inspection as a result of the damage sustained due to exhaust impacted.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions (ACHL) commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Hassan Anwar ATA VDA
Exclusive Vehicle Assessors