

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

Mr T Maples
23 St Johns Road
Peterborough
Cambridgeshire
PE2 8BL

Date: 14/11/2025
Our Ref: 00074493/PK
Your Ref: EHR90928

Engineer Repairable Report

Dear Sirs,

Client/Insured: **Mr T Maples**

We refer to your instructions received on **27 October 2025** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: HYUNDAI I20 ADVANCE T-GDI	Colour: RED	Speedo: 10581	Miles
Reg No: HK25NZJ	Registered: Jun 2025	Type: 5 Door Hatchback	Trans: Manual
Vin No: NLHBN51G8SZ621009	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Man'f'd: 2025		
Brakes: Not Known	Tax Exp:		
Steering: Not Known	Fuel: Petrol		
Extras: Not Seen	C.C.: 998	Spare Tyre Not Know	
Air Bags Deployed: Not Known	BHP: 99	Centre Belt Not Tested	
Damage: Light Accidental Damage Rear Bumper	Incident: 24/10/2025	L/H/F Belt Not Tested	L/H/R Belt Not Tested
		L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £15,700.00		Repair Cost: £911.54 inc VAT	(5.81% of PAV) Roadworthy: Yes

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light accidental damage to the rear bumper.

VEHICLE HISTORY CHECK

27/10/2025 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rear Lower Bumper

Repaint only parts:-De Nib Per Panel

Specialist/Sundry charges:-Bs10125, Car Care Kit, E.P.A. Charge, Pre Rep Diag Check, Post Rep Diag Check, Methods Research, Pas2060, Energy Supplement, ADAS Methods, Sundry Part

Remove And Refit parts:-Rear Bumper, Remove And Refit Rear Lower Bumper, Road Test And Quality Control, Specialist Wash & Vacuum

Parts to check:-Check Id ADAS

COST OF REPAIRS

The repairers, LD AutoVogue Ltd, Unit 18, 21 Ironside Way, Hingham, Norwich, NR9 4LF (Tel. 01953 454 181), have compiled an estimate in the sum of £288.00 plus parts at manufacturer's list prices plus £508.93 for specialist/sundry

charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 3.6 hours at a rate of £80.00 per hour. **We are pleased to confirm that we have achieved total gross savings in this matter of £160.27.** The cost of the necessary replacement parts will be approximately £96.25, the specialist/sundry charges will be £375.37, the VAT liability on this repair will amount to some £151.92 giving a total repair cost of £911.54 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 25/06/2025. The corresponding Glass's Guide (model code: CLCT) adjusted retail value for vehicles of this type and age in the October 2025 guide is £15,700.00 at 10581 Miles, trade value is £12,910.00 and mid value is £14,305.00. We place the pre-accident value of this particular vehicle at £15,700.00 bearing in mind the condition described herein. The following adjustments have been made to the pre-accident value;

RESERVE

We consider that a repair reserve of £925.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 14th November 2025, on your behalf.

REPAIR DURATION

We consider that this repair will take some 2 to 3 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it un roadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Exclusive Repair Network commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of

. CAE AMIMI AQP
Connexus Vehicle Assessors