


Mr Edward Kelly
35 Cottingham Drive
Northampton
NN3 7LD

Date: 17/12/2025
Our Ref: 00026892/DME
Your Ref: EHR93828 \ LV25006453550

To the Court REPAIRABLE REPORT

Dear Sirs,
Client: **Mr Edward Kelly**

We refer to your instructions received on **12 December 2025** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle:	MERCEDES-BENZ C 220 AMG LINE PRE	Colour:	White	Speedo:	14335	Miles
Reg No:	J6EDK	Registered:	Mar 2024	Type:	5 Door Estate	Trans: Automatic
Vin No:	W1KAH0EB7RF143843	MOT Exp:		R/H/F Tyre	Not Kno	R/H/R Tyre Not Kno
Mods:	Not Seen	Cond:	Unknown	R/H/F Belt	Not Tested	R/H/R Belt Not Tested
Audio:	Not Seen	Manfd:	2024			Spare Tyre
Brakes:	Not Known	Tax Exp:				Not Know
Steering:	Not Known	Fuel:				Centre Belt
Extras:	Not Seen	C.C.:	1993			Not Tested
Air Bags Deployed:	Not Deployed	BHP:	197.	L/H/F Belt	Not Tested	L/H/R Belt Not Tested
Damage:	Light to Moderate Collision/Impact LH Front Bumper	Incident:	11/12/2025	L/H/F Tyre	Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £33,313.00		Repair Cost: £3,650.64 inc VAT		(10.96% of PAV)		Roadworthy: Subject To

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF DAMAGE

The vehicle has suffered light to moderate collision impact to the left hand front bumper.

ENGINEER'S COMMENTS

I can confirm repairs have been authorised via Audatex in accordance with your original instructions.

Authority sent via Audatex.

VEHICLE HISTORY CHECK

17/12/2025 - According to the Experian database; there is a plate change on record

REPAIR SCHEDULE

New parts required:-Front Bumper, Sundries

Repairable parts:-Repair Pre Clean, Repair Shutdown, Repair Wash Vac



Repaint only parts:-Front Bumper Painting, Preparation Work For Two Coat Painting.

Specialist/Sundry charges:-Pas Uplift, Tech Data + Methods, E.P.A. Charge, Pre_Rep_Diag_Check, Post_Rep_Diag_Check, 4 Wheel Alignment, Car Care Kit, Tech Data + Methods, Adas Reset, Pas2060, Energy Payment

Remove And Refit parts:-Short Test, Battery Earth Cable, L/F Lower Cover, R/F Lower Cover, Frt Lwr Engine Compartment Cover, Front Bumper, Dis + Ass Front Bumper, Addition To Front Bumper, Add To Front Bumper Dismantle And, Addition To Front Bumper Dis + Ass, Addition To Dis + Ass Front Bumper, Addition To Front Bumper, Add For Front Bumper, Carry Out Calibration Drive, Adas Rd Test

Parts to check:-Check And Quality Control, Check And Road Test, Check Adas

COST OF REPAIRS

The repairers, QCD Revive Collision Centre (Tel. 01604 918 289), have compiled an estimate in the sum of £1,188.00 plus parts at manufacturer's list prices plus £535.53 for paint and materials plus £846.00 for specialist/sundry charges. Having calculated the time involved in this repair I consider this to be reasonable. The labour charge is based on 12 hours at a rate of £99.00 per hour. I have also agreed that the cost of paint and materials will be limited to £535.53. The cost of the necessary replacement parts will be approximately £640.67, the specialist/sundry charges will be £846.00, the VAT liability on this repair will amount to some £642.04 giving a total repair cost of £3,852.24 including VAT **subject to any undisclosed damage.**

OTHER DAMAGE

I noted the following damage on the vehicle:- Age related.

REPAIRER VAT STATUS

I am informed that the repairer is registered for VAT

PRE-INCIDENT VALUE

According to the information available to me the vehicle was first registered in 04/03/2024.

The corresponding Glass's Guide retail value for vehicles of this type and age in the December 2025 guide is £33,313.00 at 14000 Miles, trade value is £30,277.00.

I place the pre-accident value of this particular vehicle at £33,313.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

I do not consider that any betterment contribution is required on this occasion.

RESERVE

I consider that a repair reserve of £3,875.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

I am pleased to confirm that I have authorised the repairers to proceed with the work via Audatex in accordance with your instructions, on the 17th December 2025, on your behalf.

REPAIR DURATION

I consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In my opinion this vehicle was roadworthy at the time of my inspection subject to ADAS check.

For & on behalf of

TIM CLARKE

Tim Clarke IMI VDA Accreditation, C.A.E., M.I.M.I.
Exclusive Vehicle Assessors