

Mr Warren Keen
104 Thornleigh Avenue
Wirral
CH
Wirral
CH62 9BB

Date: 08/01/2026
Our Ref: 00027681/DME
Your Ref: EHR94400

To the Court REPAIRABLE REPORT

Dear Sirs,

Client: **Mr Warren Keen**

We refer to your instructions received on **23 December 2025** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: MERCEDES-BENZ AMG A 35 4MATIC PR	Colour: Grey	Speedo: 32732	Miles
Reg No: L9JDJ	Registered: Jan 2020	Type: 4 Door Saloon	Trans: Automatic
Vin No: WDD1771512J161008	MOT Exp: 	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Unknown	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manf'd: 2020		Spare Tyre Not Know
Brakes: Not Known	Tax Exp: 		Centre Belt Not Tested
Steering: Not Known	Fuel: Petrol		
Extras: Not Seen	C.C.: 1991		
Air Bags Deployed: Not Deployed	BHP: 301.	L/H/F Belt Not Tested	L/H/R Belt Not Tested
Damage: Moderate Collision/Impact RH Front Door	Incident: 22/12/2025	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £24,364.00	Repair Cost: £3,960.24 inc VAT	(16.25% of PAV)	Roadworthy: Yes

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF DAMAGE

The vehicle has suffered moderate collision impact to the right hand front door.

ENGINEER'S COMMENTS

I can confirm repairs have been authorised via Audatex in accordance with your original instructions.

Authority sent via Audatex.

VEHICLE HISTORY CHECK

07/01/2026 - According to the Experian database; there is a plate change on record

REPAIR SCHEDULE

New parts required:-R/F Wing Badge, Right Front Door, R/F Door Seal, Sundries

Repaint only parts:-Right Front Door Painting Stage I-M, R/F Wing Painting Stage Ii, R/R Door Painting Stage Ii, Add Colour Sample 1, Outer Cleaning Carry Out, Polish Vehicle, Security Measures Before, Preparation Work For Two Coat Painting, Carry Out Colour Shade Determination

Specialist/Sundry charges:-Energy Payment, Methods Research, E.P.A. Charge, Post_Rep_Diag_Check,

Pre_Rep_Diag_Check, Anti-Corrosion, Sound Pad

Remove And Refit parts:-Battery Earth Cable, Renew R/F Wing Badge, R/F Wheelhouse Liner Front, Renew R/F Door And Convert Parts, Adjust R/F Door, Right Rear Door Attached Parts, Corrosion Protection To 1St Panel

Parts to check:-Check Pre Clean, Check And Clean Car, Check And Quality Control

COST OF REPAIRS

An Audatex estimate has been obtained from Walsh Auto Engineering Ltd, 164-190 Cleveland Street Birkenhead, CH, CH41 3QQ (Tel. 0151 647 5131) in the sum of £1,376.10 labour plus parts at manufacturer's list prices plus £695.80 for paint and materials plus £288.00 for specialist/sundry charges. Having calculated the time involved in this repair I consider this to be reasonable. The labour charge is based on 13.9 hours at a rate of £99.00 per hour. I have also agreed that the cost of paint and materials will be limited to £695.80. The cost of the necessary replacement parts will be approximately £940.30, the specialist/sundry charges will be £288.00, the VAT liability on this repair will amount to some £660.04 giving a total repair cost of £3,960.24 including VAT **subject to any undisclosed damage.**

OTHER DAMAGE

I noted the following damage on the vehicle:- None noted.

REPAIRER VAT STATUS

I am informed that the repairer is registered for VAT

PRE-INCIDENT VALUE

According to the information available to me the vehicle was first registered in 31/01/2020.

The corresponding Glass's Guide retail value for vehicles of this type and age in the December 2025 guide is £24,364.00 at 32000 Miles, trade value is £21,950.00.

I place the pre-accident value of this particular vehicle at £24,364.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

I do not consider that any betterment contribution is required on this occasion.

RESERVE

I consider that a repair reserve of £3,975.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

I am pleased to confirm that I have authorised the repairers to proceed with the work via Audatex in accordance with your instructions, on the 8th January 2026, on your behalf.

REPAIR DURATION

I consider that this repair will take some 4 to 5 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In my opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

For & on behalf of



Tim Clarke IMI VDA Accreditation, C.A.E., M.I.M.I.
Exclusive Vehicle Assessors