

Mr Liam Gordon
29 Wargrave Road
Harrow
HA
Harrow
HA2 8LL


Date: 08/05/2026
Our Ref: 00031329/DME
Your Ref: EHR97578 \ P76727312-1

To the Court
REPAIRABLE REPORT - Supplementary Report

Dear Sirs,
Client: **Mr Liam Gordon**

We refer to your instructions received on **02 March 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: BMW XM PHEV AUTO	Colour: Black	Speedo: 23455 Miles
Reg No: FD23ZHP Registered: Jul 2023	Type: 5 Door Estate	Trans: Automatic
Vin No: WBS22CS0X09R54342	MOT Exp: 	R/H/F Tyre Not Kno R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested R/H/R Belt Not Tested
Audio: Not Seen	Manfd: 2023	Spare Tyre Not Known
Brakes: Not Known	Tax Exp: 	Centre Belt Not Tested
Steering: Not Known	Fuel: Hybrid	
Extras: Not Seen	C.C.: 4395	
Air Bags Deployed: Not Known	BHP: 643.	L/H/F Belt Not Tested L/H/R Belt Not Tested
Damage: Light Collision/Impact Rear Bumper	Incident: 27/02/2026	L/H/F Tyre Not Kno L/H/R Tyre Not Kno



Vehicle Value: £88,433.00	Repair Cost: £2,188.68 inc VAT (2.47% of PAV)	Roadworthy: Yes
----------------------------------	--	------------------------

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light collision/impact damage to the rear bumper.

ENGINEER'S COMMENTS

I can confirm repairs have been authorised via Audatex in accordance with your original instructions.

Authority sent via Audatex.

VEHICLE HISTORY CHECK

According to the Experian database; there is a plate change on record

REPAIR SCHEDULE

New parts required:-Repair Sundries, Sundry Parts

Repairable parts:-L/R Bumper Cover, Rr Underbody Protect



Repaint only parts:-Rear Bumper Cover Repair Paint Plastic, Machine Polish, Preparation For Pre-Painting
Specialist/Sundry charges:-Car Care Kit, Methods Research Specialist, Hybrid Charge
Remove And Refit parts:-Description, Add/Time For Main Work, Rear Bumper Trim, L/R Bumper Trim, R/R Bumper Trim, Rear Lower Protection, Specialist Veh Diag Post Check, Ev Shutdown, Specialist Adas Aware
Parts to check:-Valet Car, Quality Control, Veh Diag Pre

COST OF REPAIRS

An Audatex estimate has been obtained from LVS Coachworks, 161-164 Dukes Road Park Royal London, W, Park Royal, London, W3 0SL (Tel. 0208 9931222) in the sum of £1,393.02 labour plus parts at manufacturer's list prices plus £328.11 for paint and materials plus £76.23 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 13.52 hours at a rate of £103.06 per hour. We have also agreed that the cost of paint and materials will be limited to £328.11. The cost of the necessary replacement parts will be approximately £26.54, the specialist/sundry charges will be £76.23, the VAT liability on this repair will amount to some £364.78 giving a total repair cost of £2,188.68 including VAT **subject to any undisclosed damage.**

UNRELATED DAMAGE

We noted the following damage on the vehicle which does not appear to relate to the claim under review and we have therefore classed it as unrelated damage; None noted.

REPAIRER VAT STATUS

We are informed that the repairer is registered for VAT

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 10/07/2023. The corresponding Glass's Guide retail value for vehicles of this type and age in the February 2026 guide is £88,433.00 at 23000 Miles, trade value is £79,178.00. We place the pre-accident value of this particular vehicle at £88,433.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £2,200.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 11th March 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy.

The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions (ACHL) commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of

A handwritten signature in black ink that reads "TIM CLARKE". The signature is written in a cursive, slightly slanted style.

Tim Clarke IMI VDA Accreditation, C.A.E., M.I.M.I.
Exclusive Vehicle Assessors