

Mr Joseph Fleming-deeks
31 Bugbrooke Lane
Barton Seagrave
Ketter
NN
Barton Seagrave
NN15 4AF

Date: 22/04/2026
Our Ref: 00034290/HASSANA
Your Ref: EHR99860

To the Court REPAIRABLE REPORT

Dear Sirs,

Client: **Mr Joseph Fleming-deeks**

We refer to your instructions received on **13 April 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: TESLA MODEL 3 LONG RANGE AWD		Colour: GREY	Speedo: 44305 Miles	
Reg No: DE21KSY	Registered: Aug 2021	Type: 4 Door Saloon	Trans: Automatic	
Vin No: LRW3F7EK6MC300707	MOT Exp: 	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno	
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manfd: 2021			
Brakes: Not Known	Tax Exp: 			Spare Tyre Not Known
Steering: Not Known	Fuel: Electric			Centre Belt Not Tested
Extras: Not Seen	C.C.: 0	L/H/F Belt Not Tested	L/H/R Belt Not Tested	
Air Bags Deployed: Not Known	BHP: 469.	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno	
Damage: Light to Moderate Collision/Impact LH Front	Incident: 27/03/2026			

Vehicle Value: £16,500.00	Repair Cost: £3,081.59 inc VAT (18.68% of PAV)	Roadworthy: Yes
----------------------------------	---	------------------------

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the left hand front.

VEHICLE HISTORY CHECK

22/04/2026 - According to the Experian database; there is a plate change on record

REPAIR SCHEDULE

New parts required:-Sundry Parts

Repairable parts:-Front Bumper

Repaint only parts:-Two Coat Metallic, Front Bumper Repair Paint Plastic, Polish De Nib, Preparation For Pre-Painting

Specialist/Sundry charges:-Car Care Kit, Pas Uplift, E.P.A. Charge, Tech Data + Methods, Wheel Alignment

Blend only parts:-L/F Wing Surface Paint

Remove And Refit parts:-Description, Vehicle Preparation Time, Front Bumper, Radiator Grille, L/F Fog Lamp/Daytime Running Lamp, R/F Fog Lamp/Daytime Running Lamp, L/F Wheelarch Shell, Hybrid Vehicle Electric,



Road Test Qc, Vacuum Wash, Clean Charge Pre Estimate
Parts to check:-Veh Diag Post, Veh Diag Pre, Electric Risk Assess

COST OF REPAIRS

The repairers, Milton Keynes Motor Company (Tel. 01908 375100), have compiled an estimate in the sum of £1,782.94 plus £544.35 for paint and materials plus £240.70 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 17.3 hours at a rate of £103.06 per hour. We have also agreed that the cost of paint and materials will be limited to £544.35. No new parts are required and the specialist/sundry charges will be £240.70, the VAT liability on this repair will amount to some £513.60 giving a total repair cost of £3,081.59 including VAT **subject to any undisclosed damage.**

UNRELATED DAMAGE

We noted the following damage on the vehicle which does not appear to relate to the claim under review and we have therefore classed it as unrelated damage; rear bumper and quarter -£250.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 20/08/2021. The corresponding CAP Guide (model code: 89233) adjusted retail value for vehicles of this type and age in the March 2026 guide is £16,750.00 at 44305 Miles, trade value is £14,450.00 and mid value is £15,600.00. We place the pre-accident value of this particular vehicle at £16,500.00 bearing in mind the condition described herein. The following adjustments have been made to the pre-accident value; condition adjustment -£250.00.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £3,100.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 22nd April 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 4 to 5 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE


In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Hassan Anwar ATA VDA
Exclusive Vehicle Assessors