

Accident Date: Mon Jul 06 2026

Submission date: Mon Jul 06 2026

Case ID: 07b3ec51-c756-4243-908f-c7ae12912786

Case Details

Repair quote: £640.00 (excluding tax)

Vehicle Information

Producer	Volkswagen
Model	Touran
Type	-
Year of Production	2014
VIN	WVGZZZ1TZFW030347
Registration Number	YP64YRW
Registration Date	-
Mileage	143,875
Vehicle Value	£3,437.00

Repair Summary

Remove & Install	0.7 hours @ £65.00/hour
Panel Repair Hours	1.0 hours @ £65.00/hour
Paint Hours	0.7 hours @ £65.00/hour
Part Costs	£0.00
Paint Material Costs	£130.00
Additional Costs	£354.00

Preliminary AI quote

Panel	Operation	Part Number	Producer	Supplier	Unit cost	Qty	Hours	Paint Material	Totals (£)
Main operations									
Rear bumper							2.4		286.00
Rear bumper	Repair	-			-	1	1.7	130.00	240.50
Rear bumper	R&I	-			-	-	0.7	-	45.50
Total cost (£)									286.00

Additional operation	Qty	Unit cost	Labour Hour	Total cost (£)
Car Care Kit	1	6.50	-	6.50
Paint Preparation	1	0.00	1.7	110.50
Pre Repair Diagnostics	1	150.00	-	150.00
EPA	1	15.00	-	15.00
Tech Data and Methods	1	20.00	-	20.00
Check and Clean	1	0.00	0.5	32.50
Road Test	1	0.00	0.3	19.50
Total cost (£)				354.00

Totals	Rate	Hours	Totals (£)
Part			0.00
Labour			318.50
Paint labour	£65.00 / hr	0.7	45.50
Body labour	£65.00 / hr	4.2	273.00
Other costs			321.50
Paint material	-	-	130.00
Other costs	-	-	191.50
Total excluding tax			640.00
Tax	20%		128.00
Total including tax			768.00

Submitted Vehicle Images

