

Calculation

Client:
Make / Model / Type: Tesla / Model 3 / Model 3 RWD Aut. 2019MY [11.2021]
Glass's national Code 345245001
Vehicle Registration Number: LG73ZCJ
VIN: LRW3F7FS1PC837231
Date: 13.5.2026

Paint system: AZT
Hail damage logic: ETG
Labour time unit: 1 Hour
Currency: £
Database version: 2026.03.

Body		Repair type	Labour time	Overlap-time	Labour costs	Material costs
10013002	Rear Bumper Lining	RP	0.00	0.70		458.33
10012901	Rear Bumper Spoiler					
10017102	Rear Bumper Side Bracket (R)	RP	1.00		83.28	12.50
10013001	Rear Bumper Lining					
15244801	Rear Panel Interior Trim					
15245001	Load Compartment Interior Trim (L)					
15245101	Load Compartment Interior Trim (R)					
10016202	Rear Bumper Outer Bracket (R)	RP	0.10	0.60	8.33	16.25
10014302	Rear Bumper Support Plate	RP	0.40	0.60	33.31	28.75
NN	Rear Bumper Repair Kit	RP	0.00			0.00
NN	Rear Bumper Lining Screw	RP	0.00			0.79
NN	Rear bumper lining Nut	RP	0.00			0.42
17403502	Outer Reflector (L)	RP	0.40	0.60	33.31	12.92
17403602	Outer Reflector (R)	RP	0.40	0.60	33.31	12.92
NN	Rear Side Panel (R)	R	0.50		41.64	0.00
12011101	Side Panel Liner (L)	UI	0.00	0.20		0.00
12011201	Side Panel Liner (R)	UI	0.00	0.20		0.00
Labour costs					233.18	
Material costs						542.88
Total Body						£ 776.06

Auxiliary work		Repair type	Labour time	Overlap-time	Labour costs	Material costs
NN	Rear Side Panel Strip & Set-Up for Paint (L)	UI	0.00	1.00		0.00
12251102	Scuttle Grille					
10106501	Rear Door Shell (L)					
10013101	Rear Bumper Reinforcement					
10017101	Rear Bumper Side Bracket (L)					
10016101	Rear Bumper Outer Bracket (L)					
18105301	Side Panel Air Vent Grille (L)					
NN	Side Panel Power Socket Lid (L)					
44011651	Side Panel Power Socket (L)					
NN	Side Panel Power Socket Bracket (L)					
10203001	Side Panel Glass (Tinted) (L)					
NN	Side Glass Repair/Bonding Kit (L)					
NN	Boot Lid					
11702001	Boot Lid/Tailgate/Back Door Weatherstrip					
NN	Boot Lid/Tailgate Hinge (L)					

11334001	Gas-Filled Spring/Damper (L)					
34015201	Rear Wheel Remove & Install (L)					
15186001	C-Post Upper Interior Trim (L)					
	Annotation (time): Time includes remove & reinstall roof					
NN	Rear Side Panel Strip & Set-Up for Paint (R)	UI	0.00	1.00		0.00
10106601	Rear Door Shell (R)					
10016201	Rear Bumper Outer Bracket (R)					
18105321	Side Panel Air Vent Grille (R)					
10203101	Side Panel Glass (Tinted) (R)					
NN	Boot Lid/Tailgate Hinge (R)					
11334101	Gas-Filled Spring/Damper (R)					
34015301	Rear Wheel Remove & Install (R)					
15186101	C-Post Upper Interior Trim (R)					
	Annotation (time): Time includes remove & reinstall roof					
NN	.Assessment Damage	EC	0.00			176.96 F
	Appraisal Charge					
NN	.Environmental Charge	EC	0.00			31.23 F
NN	.Pre repair cleaning charge	EC	0.50		41.64	0.00 F
NN	.QC & Road Test	EC	1.00		83.28	0.00 F
NN	.Sundries	EC	0.00			20.00 F
NN	.System Diagnostic Check (Post Repair)	EC	1.00		83.28	0.00 F
NN	.System Diagnostic Check (Pre Repair)	EC	1.00		83.28	0.00 F
NN	.Vehicle Care Kit	EC	0.00			10.41 F
NN	.Wash/Clean	EC	1.00		83.28	0.00 F
NN	Electric / hybrid risk assessment	EC	0.50		41.64	0.00 F
NN	Electric / hybrid shutdown and power up	EC	3.00		249.84	0.00 F
NN	Electric vehicle full charge	EC	0.00			52.05 F
NN	Panel repair sundries (including body fi	EC	0.00			26.02 F
NN	Second man lift	EC	0.20		16.66	0.00 F
NN	.Yard Charge	EC	1.00		83.28	0.00 F

Labour costs

766.18

Material costs

316.67

Total Auxiliary work

£ 1,082.85

Paint	Paint type	Paint level	Labour time	Labour costs	Material costs
Rear Side Panel, Complete K/I (L)	200	B	0.60	49.97	93.50
Rear Side Panel, Complete K/I (R)	200	III	1.20	99.94	115.00
Rear Bumper k/e	200	K1R	1.10	91.61	350.50
Prep. metal (on vehicle without pre-painting)	200		1.70	141.58	114.68
Prep. synthetics (combined-operation work)	200		0.50	41.64	44.68
Colour mixing (1)			0.30	24.98	0.00
Sample colour creation (1)			0.30	24.98	11.06

Labour costs

474.70

Material costs

729.42

Total Paint

£ 1,204.12

Summary	Labour rate	Labour time	Labour costs	Material costs
Body	83.28	2.80	233.18	542.88
Auxiliary work	83.28	9.20	766.18	316.67
Paint	83.28	5.70	474.70	729.42

Total Labour

17.70

1,474.06

Total Material

1,588.97

Repair costs excl. VAT

3,063.03

VAT (20.00 %)

612.61

Repair costs incl. VAT**£ 3,675.64**

Part name	Part no.	Previous part no.	Material costs
Rear Bumper Lining	1083983SCB		458.33
Rear Bumper Side Bracket	108399300F		12.50
Rear Bumper Outer Bracket	108398900K		16.25
Rear Bumper Support Plate	112119100E		28.75
Rear Bumper Repair Kit	KET		0.00
Rear Bumper Lining Screw	105596600A		0.79
Rear bumper lining Nut	110879800C		0.42
Outer Reflector	173238100A		12.92
Outer Reflector	173238200A		12.92

Total Parts**£ 542.88**

Attention: Listed part numbers are for information only and CANNOT be used for ordering purposes.

Part name	Position no.
Rear Bumper Lining	10013002
Rear Bumper Side Bracket	10017102
Rear Bumper Outer Bracket	10016202
Rear Bumper Support Plate	10014302
Rear Bumper Repair Kit	
Rear Bumper Lining Screw	
Rear bumper lining Nut	
Outer Reflector	17403502
Outer Reflector	17403602
Rear Side Panel	
Side Panel Liner	12011101
Side Panel Liner	12011201
Rear Side Panel Strip & Set-Up for Paint	
Rear Side Panel Strip & Set-Up for Paint	
.Assessment Damage Appraisal Charge	
.Environmental Charge	
.Pre repair cleaning charge	
.QC & Road Test	
.Sundries	
.System Diagnostic Check (Post Repair)	
.System Diagnostic Check (Pre Repair)	
.Vehicle Care Kit	
.Wash/Clean	
Electric / hybrid risk assessment	
Electric / hybrid shutdown and power up	
Electric vehicle full charge	
Panel repair sundries (including body fi	
Second man lift	
.Yard Charge	

Abbreviations	Description
F	User defined operations
R	RIGHT
L	LEFT
RP	Replace
R	Repair
UI	Uninstall and install
EC	Surcharge

NN

No part number

Paint type

Paint level, Procedure, Method

B	Adjacent Panel Blend
200	2 Coat
III	Repair up to 50%
K1R	Part priming/part raw

Additional Fields

Paint material index	100.000 %
Part index	100.000 %

Glass's does not take responsibility for accuracy and completeness of data originating from vehicle manufacturers.