

QDOS Assistance
1st Floor, Barfield House
24-28 alderley Road
Wilmslow
Cheshire
SK9 1PL

Date: 27/08/2026
Our Ref: 00043766/PHILB
Your Ref: 48044/1

To the Court REPAIRABLE REPORT

Dear Sirs,
Client: **Mrs Elva Vilar**

We refer to your instructions received on **26 August 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: VAUXHALL COMBO LIFE SE TURBO D		Colour: Black	Speedo: 44992 Miles	
Reg No: MT21ZF	Registered: Apr 2021	Type: M.P.V.	Trans: Manual	
Vin No: W0VECYHT2MJ664949	MOT Exp: 	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno	
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manf'd: 2021			
Brakes: Not Known	Tax Exp: 			Spare Tyre Not Know
Steering: Not Known	Fuel: Diesel			Centre Belt Not Tested
Extras: Not Seen	C.C.: 1499			
Air Bags Deployed: Not Known	BHP: 100.	L/H/F Belt Not Tested	L/H/R Belt Not Tested	
Damage: Light to Moderate Accidental Damage LH Side	Incident: 25/08/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno	
Vehicle Value: £12,750.00		Repair Cost: £2,061.38 inc VAT (16.17% of PAV)	Roadworthy: Yes	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate accidental damage to the left hand side.

ENGINEER'S COMMENTS

The engineer has inspected this vehicle from images supplied by the principal only, the repair costs have been based on the images received and therefore may not be accurate if further damage is found, condition details and service records have not been checked in relation to the pre-accident value.

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-L/F Door Frame, Panel Sundries, Car Care Kit, Sundry Parts

Repaint only parts:-Two Coat Metallic, L/F Sill Panel New Part Painting, De Nib & Polish. Per Panel, Preparation For Pre-Painting

Specialist/Sundry charges:-Bsi Compliance, Epa, Repair Methods, Corrosion Protection Materials External

Remove And Refit parts:-Description, Renew L/F Sill Trim, Attached Parts Of The L/Sill Trim, Corrosion Prote To 1St Panel

Parts to check:-Qc & Road Test, Pre Rep Diag Scan, Post Rep Diag Scan, Wash And Vacuum

COST OF REPAIRS

No estimate has been obtained for repairing the vehicle but, **subject to further damage found during dismantling**, we have calculated the time involved in such a repair using Audatex and we consider that a reasonable labour charge would be £1,057.66. The cost of the paint and materials would be £187.52, The cost of the replacement parts would be approximately £339.16, The specialist/sundry charges would be £133.48, and the VAT liability on the total would amount to some £343.56 giving a total repair cost of £2,061.38 including VAT **subject to undisclosed damage**. The labour charge is based on 12.7 hours at a rate of £83.28 per hour.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 23/04/2021. The corresponding CAP Guide (model code: 8457565) adjusted retail value for vehicles of this type and age in the August 2026 guide is £12,750.00 at 44992 Miles, trade value is £12,622.00 and mid value is £12,686.00. We place the pre-accident value of this particular vehicle at £12,750.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £2,075.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We confirm that we have not authorised repairs on your behalf and our actions in this matter remain without prejudice.

REPAIR DURATION

We consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. QDOS Assistance commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Phil Birch ATA VDA
Exclusive Vehicle Assessors