Checklist: 3D-Printer

2021-08-25







Before

- Must remove any debris/leftover prints from bed
- **Should** clean bed (e.g. with isopropanol)

During

- Must not leave the workshop during the print; check regularly
- Must observe 1st layer

After

- Must let nozzle cool down before turning off printer
- Must remove filament from extruder (may break off if left)
- **Should** turn off slicer PC if not needed

