




ROCK BREAKER EQUIPMENT INSPECTION CHECK LIST

Annex to certificate N°: ST-4539-59

Date of inspection: 03/may/2026

	DESCRIPTION	CONDITION OR REMARKS
0	GENERAL DESCRIPTION OF THE EQUIPMENT	
0.0	Description: Rock Breaker Equipment	ROCK BREAKER EQUIPMENT Manufacturer: HITACHI MODEL: ZX200 REG NO: A 7538-Basra CHASSIS NO: HCM1G600K00112434
1	SECTION	
1.1	Manufacturers operation manual	N/A
1.2	Operator competency certificate	OK
1.3	Hand Brake Interlock	OK
1.4	Hydraulic oil level	OK
1.5	Condition of oil	OK
1.6	System and hoses	OK
1.7	Lubrication	OK
1.8	Engine Indication	OK
1.9	Boom structure	OK
1.10	Control levers	OK
1.11	Track Roller frame	OK
1.12	Wear , damage , cracks , leaks	OK
1.13	Bucket	OK
1.14	Pins , Grease lines	OK
1.15	Tracks/ Tyres / Crawler	OK
1.16	Windows / Mirrors / Lights	OK
1.17	Undercarriage (including leaks)	OK
1.18	Belts / Hoses / Bolts	OK
1.19	Electrical System	OK
1.20	Power Train	OK
1.21	Power Unit	OK
1.22	Power Link	OK
1.23	Motion Alarm	OK
1.24	Counter Weight	OK
1.25	Main Frame	OK
1.26	Fire Extinguisher	OK
1.27	First Aid	OK





ROCK BREAKER EQUIPMENT INSPECTION CHECK LIST

Annex to certificate N°: ST-4539-59

Date of inspection: 03/may/2026

Comment:



Surveyor's Name: Mohamed Abdel Halim

Signature



Certificate of Thorough Examination & NDE for Hydraulic Rock Breaker

Date of Through Examination: 03/may/2026	Certificate number: ST-4539-59
Name and Address of employer: MSK Co., BASRA , IRAQ	
Address of premises at which the examination was made: MSK YARD	

Identification NO	QTY	Description	Date of next exam
HCM1G600K00112434	1	ROCK BREAKER EQUIPMENT MANUFACTURER: HITACHI MODEL: ZX200 REG NO: A 7538-Basra CHASSIS NO: HCM1G600K00112434 BREAKER S/N: 05 EXAMINED IN ACCORDING TO BS EN 474-5:2006+A3:2013	02/May/2027

Tools Details	
Measuring Tape S/N: SCP-L-001	Vernier Calliper S/N: SCP-L-002

NDT Details		
Standard: BS EN ISO 9934-1	Equipment type: YOKE S\N: 3291K	Contrast Media: WHITE
Procedure: SPS-IMS-P027	Method: WET	Indicator: MAG INK

Result MPI was carried out on the critical stress areas of breaker were found free from any surface defects

					Was the examination carried out:			
Is this the first examination after installation or assembly at a new site or location?	YES	NO	✓		Within an interval of 6 months?	YES	NO	✓
					Within an interval of 12 months?	YES	✓	NO
If the answer to the above question is YES, has the equipment been installed correctly?	YES	NO			In accordance with an examination scheme?	YES	✓	NO
					After the occurrence of exceptional circumstances?	YES	NO	✓

Identification of any part found to have a defect: (NONE)
 Particulars of any repair, renewal or alteration required: (NONE)
 Particulars of any tests carried out: (Visual, Function, Performance, MPI Tests)

Is This Equipment Safe To Operate?	YES	✓	NO	
------------------------------------	-----	---	----	--

Name of person making this report:
 Mohamed Abdel Halim

Signature:



Name of person authenticating this report:
 Mostafa Shama

Signature:



Name of employer of persons making and authenticating this report:

Scope petroleum services: lifting@scopeps.com
 Address: Burjesia-Tuba Area -After the Bridge Hamoud El-Wabdan
 Contacts: operation@scopeps.com/sales@scopeps.com
 Phone: +964 7803222202 / +964 7803773775