Answers and marking guidance

Award one mark per correct, developed point unless stated. Other valid answers should be credited.

2 State two features that show the casing was injection moulded.

- Split line where the mould halves met
- Ejector pin marks (small circles)
- Injection point (sprue mark)
- Draft angles on the sides
- Flashing, if not trimmed
- Bosses, ribs or location pins moulded in

No marks for: "Smooth" or "shiny" on their own

3 Quick check

- a) To take a screw and strengthen the fixing point
- b) Accurate assembly
- c) Add rigidity without thick walls and hold internal parts
- d) Flashing

4 Key terms

- 1 – B
- 2 – D
- 3 – A
- 4 – C

5 Explain what is meant by ‘Split line’.

- Line where two halves of a mould meet.

6 Explain what is meant by ‘Shear marks’.

- Marks on edges cut by piercing or blanking.