Report ID: MAXIA20230729133633 Test Time: 2023-07-29 13:36:33

Technician: --

## **Benz Vehicle Diagnostic Report**

Vehicle Information

--/Benz/253.381 - GLC 200 4MATIC Coupe / GLC 260 4MATIC

VIN: W1N2533811F770597

**Customer Information** 

Name: --

Device information

Scanner: MaxiPRO MP808BT PRO

Version: V1.41

Odometer Reading: 32553km

License Plate: --

Tel: --

Serial Number: VP2GNAC01210

Repair Order Number: VP2GNAC0121020230729132743369

## System Scanned( 48 )

System	Status/DTC
ECM(Engine Control Unit)	0
TCM(Transmission Control Unit)	<b>②</b> 0
ESP(Electronic Stability Program Braking System)	<b>②</b> 0
SRS(Supplemental Restraint System Control Unit)	<b>②</b> 0
LIN:WSS-1(Weight Sensing Sensor Control Unit)	<b>②</b> 0
KI(Instrument Cluster)	<b>②</b> 0
TPM(Tire Pressure Monitor Control Unit)	<b>②</b> 0
PTS(Parking System)	<b>②</b> 0
SAMF(Front Signal Acquisition Control Unit)	<b>②</b> 0
LIN:BSN(Battery Sensor)	<b>②</b> 0
LIN:FSW(Wiper Motor)	<b>O</b>
LIN:VCS(Rain/Light Sensor)	<b>②</b> 0
SAMR(Rear Signal Acquisition Control Unit)	<b>②</b> 0
LIN:SHM_F(Front Seat Heating/Ventilation Control Unit)	<b>②</b> 0
EZS(Electronic Ignition Lock Control Unit)	<b>②</b> 0
KLA(Air Conditioner Control Unit)	<b>②</b> 0
PTCU(Drivetrain Control Unit)	<b>②</b> 0
Benz/ 253.381 - GLC 200 4MATIC Coupe / GLC 260 4MATIC Coupe/	<b>②</b> 0

AUTEL www.autel.com

MaxiPRO MP808BT PRO

/Benz/253.381 - GLC 200 4MATIC Coupe / GLC 260 4MATIC	Test Time: 2023-07-29 13:36:33	Report ID: MAXIA20230729133633
HU(Head Unit Control Unit)		<b>O</b>
KG(Keyless Go Control Unit)		<b>O</b>
SW-SW-R(Right Headlamp)		<b>O</b>
SW-SW-L(Left Headlamp)		<b>②</b> 0
LRE(Steering Wheel Electronics)		<b>O</b>
ABA(Front Radar Sensor)		<b>②</b> 0
DMFL(Left Front Door Control Unit)		<b>O</b>
DMFR(Right Front Door Control Unit)		<b>②</b> 0
DMRR(Right Rear Door Control Unit)		<b>②</b> 0
DMRL(Left Rear Door Control Unit)		<b>②</b> 0
TPAD(Touch Head Unit Controller)		<b>②</b> 0
LIN:OBF_1(Upper Control Panel)		<b>②</b> 0
LIN:UBFR_1(Head Unit Controller Right Button)		<b>②</b> 0
LIN:UBF_1(Lower Control Panel)		<b>②</b> 0
ZAN(Center Display Control Unit)		<b>②</b> 0
SG-EM-1(Power Electronics Control Unit)		<b>②</b> 0
MRM(Steering Column Control Unit)		<b>②</b> 0
MFK(Multifunction Camera)		<b>②</b> 0
IRS-HRA(Right Rear Outer Driving Assist Radar)		<b>②</b> 0
IRS-HLA(Left Rear Outer Driving Assist Radar)		<b>②</b> 0
HKS(Trunk Lid Control Unit)		<b>②</b> 0
FSCU(Fuel Pump Control Unit)		<b>②</b> 0
ES(Electric Power Steering)		<b>②</b> 0
DTA(Telematics Service Control Unit)		<b>②</b> 0
DDW(DC/DC Converter Control Unit)		<b>②</b> 0
LIN:LBMS-48(48V Lithium-Ion Battery)		<b>②</b> 0
Benz/ 253.381 - GLC 200 4MATIC Coupe / GLC 260 4MATIC Co	oupe/	<b>②</b> 0
LIN:AISP_1(Interior Rearview Mirror)		<b>②</b> 0

AUTEL www.autel.com MaxiPRO MP808BT PRO Page 2

/Benz/253.381 - GLC 200 4MATIC Coupe / GLC 260 4MATIC	Test Time: 2023-07-29 13:36:33	Report ID: MAXIA2023072913363
LIN:GTO_1(Rearview Mirror Garage Door Opener)		<b>O</b> 0
AML(Ambient Lighting Lamp)		<b>O</b>
AHE(Trailer Recognition)		<b>②</b> 0
DTC(0)		

Technician Notes

Customer name:	
Technician:	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



www.autel.com