

Shop: --Tel: --Email: --Address: --

Report ID: MAXIA20230729133633 Test Time: 2023-07-29 13:36:33

Technician: --

Benz Vehicle Diagnostic Report

Vehicle Information

--/Benz/253.381 - GLC 200 4MATIC Coupe / GLC 260 4MATIC

Coupe/

VIN: W1N2533811F770597

Customer Information

Name: -- Tel: --

Device information

Scanner: MaxiPRO MP808BT PRO Serial Number: VP2GNAC01210

Version: V1.41 Repair Order Number:

VP2GNAC0121020230729132743369

Odometer Reading: 32553km

License Plate: --

System Scanned (48)

System Scanned (40)	
System	Status/DTC
ECM(Engine Control Unit)	② 0
TCM(Transmission Control Unit)	② 0
ESP(Electronic Stability Program Braking System)	② 0
SRS(Supplemental Restraint System Control Unit)	② 0
LIN:WSS-1(Weight Sensing Sensor Control Unit)	② 0
KI(Instrument Cluster)	O
TPM(Tire Pressure Monitor Control Unit)	② 0
PTS(Parking System)	② 0
SAMF(Front Signal Acquisition Control Unit)	Q 1
LIN:BSN(Battery Sensor)	② 0
LIN:FSW(Wiper Motor)	O
LIN:VCS(Rain/Light Sensor)	② 0
SAMR(Rear Signal Acquisition Control Unit)	② 0
LIN:SHM_F(Front Seat Heating/Ventilation Control Unit)	② 0
EZS(Electronic Ignition Lock Control Unit)	O
KLA(Air Conditioner Control Unit)	② 0
PTCU(Drivetrain Control Unit)	② 0

Benz/ 253.381 - GLC 200 4MATIC Coupe / GLC 260 4MATIC Coupe/	Test Time: 2023-07-29 13:36:33	Report ID: MAXIA20230729133633
HU(Head Unit Control Unit)		② 0
KG(Keyless Go Control Unit)		② 0
SW-SW-R(Right Headlamp)		② 0
SW-SW-L(Left Headlamp)		② 0
LRE(Steering Wheel Electronics)		② 0
ABA(Front Radar Sensor)		② 0
DMFL(Left Front Door Control Unit)		② 0
DMFR(Right Front Door Control Unit)		② 0
DMRR(Right Rear Door Control Unit)		② 0
DMRL(Left Rear Door Control Unit)		② 0
TPAD(Touch Head Unit Controller)		② 0
LIN:OBF_1(Upper Control Panel)		② 0
LIN:UBFR_1(Head Unit Controller Right I	Button)	② 0
LIN:UBF_1(Lower Control Panel)		② 0
ZAN(Center Display Control Unit)		② 0
SG-EM-1(Power Electronics Control Uni	t)	② 0
MRM(Steering Column Control Unit)		② 0
MFK(Multifunction Camera)		② 0
IRS-HRA(Right Rear Outer Driving Assis	t Radar)	② 0
IRS-HLA(Left Rear Outer Driving Assist	Radar)	② 0
HKS(Trunk Lid Control Unit)		② 0
FSCU(Fuel Pump Control Unit)		② 0
ES(Electric Power Steering)		② 0
DTA(Telematics Service Control Unit)		② 0
DDW(DC/DC Converter Control Unit)		② 0
LIN:LBMS-48(48V Lithium-Ion Battery)		② 0

MaxiPRO MP808BT PRO

Page 2

Benz/ 253.381 - GLC 200 4MATIC Coupe / GLC 260 4MATIC Coupe/	Test Time: 2023-07-29 13:36:33	Report ID: MAXIA20230729133633
DBE(Sunroof Control Unit)		② 0
LIN:AISP_1(Interior Rearview Mirror)		• 0
LIN.AISP_I(IIIterior Realview WillTor)		② 0
LIN:GTO_1(Rearview Mirror Garage Do	oor Opener)	② 0
Env. 610_1 (near view wint of darage be	of Opener)	
AML(Ambient Lighting Lamp)		② 0
, 3 3 17		
AHE(Trailer Recognition)		② 0
TO (1)		

🖴 DIG(I)

SAMF(Front Signal Acquisition Control Unit) (1 DTC)

DTC	Description	Status
B23267B	Fill level sensor 'Washer fluid level' has a malfunction. The fluid level is too low.	Active and stored(Event codes)

Technician Notes

Customer name:	
Technician: .	
Date: .	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiPRO MP808BT PRO Page 3