

Shop: --Tel: --Email: --

Address: --

Report ID: MAXIA20230704171846 Test Time: 2023-07-04 17:18:46

Technician: --

# Benz Vehicle Diagnostic Report

**Vehicle Information** 

--/Benz/205.040 - C 180 Sedan / C 200 Sedan/

VIN: WDD2050401R360273

**Customer Information** 

Name: --

**Device information** 

Scanner: MaxiPRO MP808BT PRO

Version: V1.41

Odometer Reading: 108380km

License Plate: --

Tel: --

101.

Serial Number: VP2GNAC01210

Repair Order Number:

VP2GNAC0121020230704171330183

## System Scanned (35)

| System   | Status/DTC |
|--|------------|
| ECM(Engine Control Unit)                               | <b>②</b> 0 |
| TCM(Transmission Control Unit)                         | <b>O</b>   |
| ESP(Electronic Stability Program Braking System)       | <b>②</b> 0 |
| SRS(Supplemental Restraint System Control Unit)        | <b>②</b> 0 |
| LIN:WSS-1(Weight Sensing Sensor Control Unit)          | <b>②</b> 0 |
| KI(Instrument Cluster)                                 | <b>O</b>   |
| TPM(Tire Pressure Monitor Control Unit)                | <b>②</b> 0 |
| PTS(Parking System)                                    | <b>O</b>   |
| SAMF(Front Signal Acquisition Control Unit)            | <b>Q</b> 1 |
| LIN:BSN(Battery Sensor)                                | <b>O</b>   |
| LIN:DBE-1(Sunroof Control Unit)                        | <b>O</b>   |
| LIN:FSW(Wiper Motor)                                   | <b>O</b>   |
| LIN:VCS(Rain/Light Sensor)                             | <b>②</b> 0 |
| SAMR(Rear Signal Acquisition Control Unit)             | <b>O</b>   |
| LIN:SHM_F(Front Seat Heating/Ventilation Control Unit) | <b>O</b>   |
| EZS(Electronic Ignition Lock Control Unit)             | <b>O</b>   |
| KLA(Air Conditioner Control Unit)                      | <b>O</b>   |
| PTCU(Drivetrain Control Unit)                          | <b>②</b> 0 |
|  |            |

MaxiPRO MP808BT PRO

| Benz/ 205.040 - C 180 Sedan / C 200 Sedan/         | Test Time: 2023-07-04 17:18:46 | Report ID: MAXIA20230704171846 |
|--|--------------------------------|--------------------------------|
| HU(Head Unit Control Unit)                         |                                | <b>②</b> 0                     |
| SW-SW-R(Right Headlamp)                            |                                | <b>O</b>                       |
| SW-SW-L(Left Headlamp)                             |                                | <b>Q</b> 1                     |
| ABA(Front Radar Sensor)                            |                                | <b>O</b>                       |
| DMFL(Left Front Door Control Unit)                 |                                | <b>②</b> 0                     |
| DMFR(Right Front Door Control Unit)                |                                | <b>②</b> 0                     |
| DMRR(Right Rear Door Control Unit)                 |                                | <b>②</b> 0                     |
| DMRL(Left Rear Door Control Unit)                  |                                | <b>②</b> 0                     |
| ZBE(Head Unit Display)                             |                                | <b>②</b> 0                     |
| LIN:OBF(Upper Control Panel)                       |                                | <b>②</b> 0                     |
| LIN:UBF(Lower Control Panel)                       |                                | <b>②</b> 0                     |
| LIN:UBFR(Head Unit Controller Right Button)        |                                | <b>②</b> 0                     |
| TPAD(Touch Head Unit Controller)                   |                                | <b>②</b> 0                     |
| ZAN(Center Display Control Unit)                   |                                | <b>②</b> 0                     |
| MRM(Steering Column Control Unit)                  |                                | <b>②</b> 0                     |
| FSCU(Fuel Pump Control Unit)                       |                                | <b>②</b> 0                     |
| ES(Electric Power Steering)                        |                                | <b>②</b> 0                     |
| <b>™</b> DTC (2)                                   |                                |                                |
| SAMF(Front Signal Acquisition Control Unit) (1 DTC | 2)                             |                                |
| DTC Description                                    |                                | Status                         |

| DIC         | Description   | Status                         |
|-------------|---|--------------------------------|
| B23267B     | Fill level sensor 'Washer fluid level' has a malfunction. The fluid level is too low. | Active and stored(Event codes) |
| SW-SW-L(Lef | t Headlamp) ( 1 DTC )   |                                |
| DTC         | Description   | Status                         |
| U11A300     | Communication with 'Multifunction camera' has a malfunction.                          | Active and stored              |

MaxiPRO MP808BT PRO Page 2



### **Technician Notes**

| Customer name: |  |
|----------------|--|
|                |  |
| Technician:    |  |
|                |  |
| Date:          |  |

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiPRO MP808BT PRO Page 3