




peak (solid) and RMS (dashed) joint torque



reliability at the operating point



peak (solid) and RMS (dashed) joint torque



what the cables are asked for

