

After the modification, the baud clock on the system bus is buffered by the 74HC125