

Sensitivity =
$$\sigma \sqrt{\tau_{\text{meas}}}$$

 $\approx 100 \text{ nT}/\sqrt{\text{Hz}}$

 $\tau_{\rm meas}$: Time to perform one measurement (given here by the low pass filter of the lock-in amplifier)