

**Most decoration businesses
run at 3 to 4 Sigma.
Here's what that costs.**

What Sigma is

Sigma measures how often you turn out a defect.
Higher Sigma, fewer defects per million.

3σ **93.3%**

66,807 DPMO

1 in 15 garments has a visible fault



4σ **99.4%**

6,210 DPMO

~6 defects per 1,000



5σ 99.98%

233 DPMO

233 defects per million



6σ 99.9997%

3.4 DPMO

3.4 defects per million



99.6%

fewer defects,
moving 3σ to 5σ

3σ $\longrightarrow$ 5σ

That's process, not a new heat press.

The full playbook is on the site, free.

decodedops.co.uk

No jargon. No vendor agenda.