

39

Total Items

39

Completed

6

Issues Found

1

Add-Ons

Customer Information

Name

Taylor Reed

Email

TaylorReed@gmail.com

Address

8472 Maple Ridge Dr, St. Louis, MO 63129

Technician

Chris Dalton

Date

2026-05-10

Equipment

Service Type: furnace

Brand: Goodman

Model #: GMES800805CN

Serial: 2104F7K91234

Age: 12

Service Type: ac

Brand: Goodman

Model #: GSXH503610

Serial: 2019C3L55678

Age: 12

Add-Ons

★ **Compressor blanket**

\$150

Reduce outdoor unit noise by up to 50% and protect your compressor from harsh weather. Extend equipment life while keeping your outdoor space peaceful. Great for units near bedrooms or patios.

General Notes

The flame sensor has light buildup and should be cleaned to help prevent ignition issues or furnace lockouts. The air filter is dirty and should be replaced. A dirty filter can restrict airflow and cause the system to work harder than normal. The blower squirrel cage has some dust buildup. Cleaning is recommended to improve airflow and overall system efficiency. The UV light bulb appears aged and may need replacement soon to maintain proper performance. Airflow appears slightly restricted, likely due to the dirty filter and dust buildup. Recommend replacing the filter and monitoring system performance. The outdoor condenser coil has light debris buildup. Cleaning is recommended to help maintain proper cooling performance and efficiency.

Inspection Checklist

Issues Found

Inspect Air Filter

Severity 5/10

Notes: Air filter is dirty and should be replaced. A dirty filter can restrict airflow and cause the system to work harder than normal.

Check For Airflow Concerns

Severity 5/10

Notes: Airflow appears slightly restricted, likely due to the dirty air filter and dust buildup. Recommend replacing filter and monitoring system performance.

Inspection Of Squirrel Cage

Severity 4/10

Notes: Squirrel cage has some dust buildup. Recommend cleaning during future service to improve airflow and efficiency.

Inspect UV Light Condition

Severity 4/10

Notes: UV light condition was checked. Bulb appears aged and may need replacement soon for proper performance.

Clean Condenser

Severity 4/10

Notes: Condenser coil has light debris buildup. Recommend cleaning to help maintain proper cooling performance and efficiency.

Inspect Flame Sensor

Severity 3/10

Notes: Flame sensor has light buildup and should be cleaned to help prevent ignition issues or furnace lockouts.

Not Completed

All items were checked off.