

21

Total Items

21

Completed

3

Issues Found

1

Add-Ons

Customer Information

Name

Taylor Reed

Email

TaylorReed@gmail.com

Address

8472 Maple Ridge Dr, St. Louis, MO 63129

Technician

Chris Dalton

Date

2026-01-20

Equipment

Service Type: furnace**Brand:** Goodman**Model #:** GMES800805CN**Serial:** 2104F7K91234**Service Type:** ac**Brand:** Goodman**Model #:** GSXH503610**Serial:** 2019C3L55678

Add-Ons

★ Compressor blanket

\$150

Reduce outdoor unit noise by up to 50% and protect your compressor from harsh weather. Extend equipment life while keeping your outdoor space peaceful. Great for units near bedrooms or patios.

General Notes

Cleaned flame sensor and verify flame signal Flushed and cleared condensate drain and trap Leak was found at the outdoor unit's service valve. Technician recommends replacing the service valve, evacuating the system, and recharging to manufacturer specifications. The client asked about reducing noise from the outdoor condenser unit. The technician recommends installing a compressor sound blanket to help dampen sound and vibration during operation.

Inspection Checklist

Issues Found

Check Exterior Coils And Line Set For Refrigerant Leaks

Severity 10/10

Notes: Oily residue near outdoor service valve; cooling temps not matching expected.

Inspect Flame Sensor

Severity 8/10

Notes: Heavy oxidation; weak flame signal; occasional delayed ignition.

Clear Condensate Pan Of Debris And Flush Drain

Severity 6/10

Notes: Slow drain; debris in trap; water starting to pool.

Not Completed

All items were checked off.