

PREPARED BY

TorqueMech Mobile Repair

Mechanic: Alex Rivera
Phone: 555-0100

Mobile repair estimate prepared after initial inspection. Parts availability and vehicle condition may affect final timing.

VEHICLE

2016 Lexus GX

Estimate prepared for customer review and approval.

Repair Services (1)

Professional estimate line items with status, notes, and totals

Timing Chain Tensioner Replacement With Startup Rattle
Diagnosis and Oil Leak Inspection

\$900
Line total

Status: Urgent

Labor \$600 | Parts \$265 | Travel \$35 | 4.8 labor hrs | \$125/hr

Estimate note

Price may vary if rust, seized hardware, broken bolts, stuck fasteners, or additional diagnosis is required.

Inspection notes

Startup rattle is present after overnight cold soak. Confirm oil level, timing cover seepage, and tensioner access before final repair.

ESTIMATE SUMMARY

Estimated Total

\$900

Includes quoted services, labor, parts, travel, and selected PDF details.
1 quoted service ready for customer review.

Customer estimate total

Final price may vary based on vehicle condition, seized hardware, rust, additional diagnostics, or unseen issues discovered during repair.

Customer Reviewed Estimate

Customer reviewed the estimate details. No signature was captured.
No payment is collected or recorded on this PDF.
Customer: Jordan Customer
Phone: 555-0184

Customer-facing notes

Customer-facing notes preserved for review. Estimate is not a final invoice.