Customer Complaint 8D Report - Bracket Assembly - Section 1: Executive Summary & Scope

Eight-discipline problem-solving report addressing a customer field complaint on a bracket assembly fatigue failure. Section 1 (Executive Summary & Scope) applies to Quality Assurance within Manufacturing Knowledge Hub and is maintained by Linda Park. Defines the operational charter, scope boundaries, and executive accountability.

Operational requirement 1.1: D3 containment: all finished goods inventory of the affected lot was quarantined. Secondary control 1.2: D4 root cause: weld penetration depth fell below spec on a subset of fixtures.

- D3 containment: all finished goods inventory of the affected lot was quarantined.
- D4 root cause: weld penetration depth fell below spec on a subset of fixtures.
- Section 1 review cadence is tracked by Linda Park under Quality Assurance governance.

Control Area	Owner	Target SLA	Verification Status
Quality Assurance	Linda Park	5 business days	Verified
Customer Complaint 8D Report Gate 1	Linda Park	3 business days	Active
Customer Complaint 8D Report Gate 2	Linda Park	10 business days	Monitored

Customer Complaint 8D Report - Bracket Assembly - Section 2: Architecture & Process Flow

Eight-discipline problem-solving report addressing a customer field complaint on a bracket assembly fatigue failure. Section 2 (Architecture & Process Flow) applies to Quality Assurance within Manufacturing Knowledge Hub and is maintained by Linda Park. Maps end-to-end process stages, handoff gates, and system-of-record integrations.

Operational requirement 2.1: D4 root cause: weld penetration depth fell below spec on a subset of fixtures. Secondary control 2.2: D5 corrective action: fixture rework and weld parameter revalidation completed.

- D4 root cause: weld penetration depth fell below spec on a subset of fixtures.
- D5 corrective action: fixture rework and weld parameter revalidation completed.
- Section 2 review cadence is tracked by Linda Park under Quality Assurance governance.

Control Area	Owner	Target SLA	Verification Status
Quality Assurance	Linda Park	5 business days	Verified
Customer Complaint 8D Report Gate 1	Linda Park	3 business days	Active
Customer Complaint 8D Report Gate 2	Linda Park	10 business days	Monitored
Sec-2	Linda Park	3 business days	Stage 2 Verified



Source: Manufacturing Knowledge Hub knowledge base | SharePoint Online

Customer Complaint 8D Report - Bracket Assembly - Section 3: Governance Standards & Controls

Eight-discipline problem-solving report addressing a customer field complaint on a bracket assembly fatigue failure. Section 3 (Governance Standards & Controls) applies to Quality Assurance within Manufacturing Knowledge Hub and is maintained by Linda Park. Establishes mandatory compliance controls, approval thresholds, and audit evidence.

Operational requirement 3.1: D5 corrective action: fixture rework and weld parameter revalidation completed. Secondary control 3.2: D8 closure confirmed after 60 days of clean field performance data.

- D5 corrective action: fixture rework and weld parameter revalidation completed.
- D8 closure confirmed after 60 days of clean field performance data.
- Section 3 review cadence is tracked by Linda Park under Quality Assurance governance.

Control Area	Owner	Target SLA	Verification Status
Quality Assurance	Linda Park	5 business days	Verified
Customer Complaint 8D Report Gate 1	Linda Park	3 business days	Active
Customer Complaint 8D Report Gate 2	Linda Park	10 business days	Monitored
Sec-3	Linda Park	10 business days	Stage 3 Verified

Customer Complaint 8D Report - Bracket Assembly - Section 4: Operational KPIs & Benchmarks

Eight-discipline problem-solving report addressing a customer field complaint on a bracket assembly fatigue failure. Section 4 (Operational KPIs & Benchmarks) applies to Quality Assurance within Manufacturing Knowledge Hub and is maintained by Linda Park. Tracks baseline performance, target SLAs, and quarterly benchmark progression.

Operational requirement 4.1: D8 closure confirmed after 60 days of clean field performance data. Secondary control 4.2: D3 containment: all finished goods inventory of the affected lot was quarantined.

- D8 closure confirmed after 60 days of clean field performance data.
- D3 containment: all finished goods inventory of the affected lot was quarantined.
- Section 4 review cadence is tracked by Linda Park under Quality Assurance governance.

Control Area	Owner	Target SLA	Verification Status
Quality Assurance	Linda Park	5 business days	Verified
Customer Complaint 8D Report Gate 1	Linda Park	3 business days	Active
Customer Complaint 8D Report Gate 2	Linda Park	10 business days	Monitored
Sec-4	Linda Park	5 business days	Stage 4 Verified



Source: Manufacturing Knowledge Hub knowledge base | SharePoint Online

Customer Complaint 8D Report - Bracket Assembly - Section 5: Appendix, Lineage & Sign-off

Eight-discipline problem-solving report addressing a customer field complaint on a bracket assembly fatigue failure. Section 5 (Appendix, Lineage & Sign-off) applies to Quality Assurance within Manufacturing Knowledge Hub and is maintained by Linda Park. Records document lineage, governance metadata, version history, and owner sign-off.

Operational requirement 5.1: D3 containment: all finished goods inventory of the affected lot was quarantined. Secondary control 5.2: D4 root cause: weld penetration depth fell below spec on a subset of fixtures.

- D3 containment: all finished goods inventory of the affected lot was quarantined.
- D4 root cause: weld penetration depth fell below spec on a subset of fixtures.
- Section 5 review cadence is tracked by Linda Park under Quality Assurance governance.

Control Area	Owner	Target SLA	Verification Status
Quality Assurance	Linda Park	5 business days	Verified
Customer Complaint 8D Report Gate 1	Linda Park	3 business days	Active
Customer Complaint 8D Report Gate 2	Linda Park	10 business days	Monitored
Sec-5	Linda Park	3 business days	Stage 5 Verified