



CS710S Firmware and Demo App Software Release Notes

2026 June 25

Firmware Release Notes:

- 1. Atmel IC Firmware**
- 2. Bluetooth IC Firmware**
- 3. RFID Firmware**

Demo App Software Github Site Links (Release Notes and Source Codes for Download)

Contents

Contents 2

Atmel IC Firmware..... 3

Bluetooth IC Firmware:..... 9

RFID Firmware (from Impinj) 11

PC USB App..... 12

GitHub Site for CSL Demo Apps 13

Atmel IC Firmware

!!!! There are 3 firmware release history tracks, one is compatible with Impinj RFID Firmware V1.2.0, one is compatible with Impinj RFID Firmware V2.0.0. One is compatible with Impinj RFID Firmware V2.1.0, V2.1.1 and V2.1.2 (latest one) !!!!!

1) Impinj RFID Firmware V2.2.0 and later

Atmel Image App Compatible with Impinj Ex10 RFID Firmware V2.2.2		
Release version	Changes	Date
2.2.3	● Add BT HID barcode support.	2026-05-15
2.2.2	● Add over the air firmware upgrade support	2026-01-13
2.2.1	● RFID firmware 2.2.x support	2025-11-18

2) Impinj RFID Firmware V2.1.0, V2.1.1, V2.1.2 and later releases compatible:

Atmel Image App Compatible with Impinj Ex10 RFID Firmware V2.1.0, V2.1.1, V2.1.2		
Release version	Changes	Date
2.1.22	● Add BT HID barcode support.	2026-06-16
2.1.21	● Add over the air firmware upgrade support	2026-01-27
2.1.20	● Ignore 0x11 error	2025-10-31
2.1.19	● Add -2 TH support.	2025-10-16
2.1.18	● Power boost default off.	2025-09-25
2.1.17	● Fix Gen2x autoset mode.	2025-09-18
2.1.16	● Fix XPC problem.	2025-09-05
2.1.15	● Add Gen2X autoset mode support (5xxx).	2025-09-02
2.1.14	● Change default HID speed to basic mode.	2025-06-17
2.1.13	● Add Impinj Gen2X inventory support.	2025-05-19
2.1.12	● Fix slow HID output rate for ETSI.	2025-05-16
2.1.11	● Change regulatory max power to 3200.	2025-05-09
2.1.10	● Remove unused packet in BT HID mode	2025-04-28
2.1.9	● Modify the China frequency ● Add one more prefix in HID mode ● Add vibration when BT is connected ● Add normal HID mode	2025-04-25
2.1.8	● Add OEM power up default register and BLE HID mode. ● Status LED will be flashing when battery level is under 3.45V	2025-04-09
2.1.7	● Add LED flashing for CW On, Random On, ETSI burst On test.	2025-03-11
2.1.6	● Add custom regulatory time control.	2025-03-06

2.1.5	● Fix incorrect battery voltage measurement.	2025-01-22
2.1.4	● Fix incorrect initial power mode. ● Fix cannot control PA pin after power ramp-up failure.	2025-01-17
2.1.3	● Add autoset rfmodes (1120, 1220, 1320, 1420) support for multi-bank inventory.	2025-01-07
2.1.2	● Add autoset rfmodes (1120, 1220, 1320, 1420) support.	2025-01-06
2.1.1	● Add inventory trigger mode control for USB connection.	2024-11-13
2.1.0	● Support E710 2.1.0 RFID firmware from Impinj.	2024-10-22

3) Impinj RFID Firmware V2.0.0 compatible:

Atmel Image App Compatible with RFID Firmware V2.0.0 Release Notes		
Release version	Changes	Date
2.0.9	● Add inventory statistics miscellaneous event.	2024-09-27
2.0.8	● Modify the Taiwan frequency to new NCC regulation	2024-08-20
2.0.7	● Modify the MultibankReadConfig register.	2024-06-13
2.0.6	● Fix CW frequency channel incorrect	2024-04-26
2.0.5	● Fix hopping frequency channel incorrect	2024-04-25
2.0.4	● Change Tx On time to 1000ms for ETSI lower and upper band.	2024-04-17
2.0.3	● Multibank inventory will return epc even if read failed	2024-04-15
2.0.1	● Fix no access reply when kill command succeeds	2023-10-19
2.0.0	● Initial Release ● Compatible with the Impinj RFID Firmware 2.0 framework ● From this version and higher, Can only work with RFID Firmware 2.0 or after, NOT compatible with RFID Firmware 1.2	2023-09-04

4) Impinj RFID Firmware V1.2.0 compatible:

Atmel Image App Compatible with RFID Firmware V1.2.0 Release Notes		
Release version	Changes	Date
0.2.20	● Change Tx On time to 1000ms for ETSI lower and upper band. ● Multibank inventory will return epc even if read failed ● Fix no access reply when kill command succeeds	2024-04-26
0.2.19	● Multibank inventory will return epc even if read failed	2023-07-31
0.2.18	● Add access inventory commands 0x1A07 and 0x1A08. (Protected mode inventory)	2023-07-03
0.2.17	● Fix no access reply when kill command succeeds	2023-05-31
0.2.16	● Add 16 antenna ports support	2023-05-30
0.2.15	● Fix multiple bank inventory wrong return data	2023-05-08
0.2.14	● Add RSSI filter for multi-bank inventory	2023-05-03
0.2.13	● Add ETSI burst test.	2023-04-28
0.2.12	● Modify country Philippines frequency band.	2023-02-23
0.2.11	● Modify country India frequency band.	2023-02-20
0.2.10	● Add country enum 160 (Vietnam3).	2023-02-16
0.2.9	● Fix country -7 frequency.	2023-01-27
0.2.8	● Fix vibrator off bug.	2022-12-23
0.2.7	● Fix fastid in compact mode.	2022-11-04
0.2.6	● Fix CW ON test hang	2022-10-28
0.2.5	● Add register 0x3946 ReversePowerADC.	2022-10-26
0.2.4	● Add Authenticate command support.	2022-10-13
0.2.3	● Fix RX gain default values.	2022-09-21
0.2.2	● Fix trigger button initial state.	2022-09-13
0.2.1	● Fix multibank inventory hang.	2022-06-17

0.2.0	Support E710 1.02 firmware. Initial Release	2022-06-16
-------	---	------------

Atmel Bootloader Release Notes

Release version	Changes	Date
0.1.2	Initial version	2022-02-28

Bluetooth IC Firmware:

For Texas Instruments CC2652 R7 or CC2652 R74 Bluetooth IC (9 th character of product serial number must be "B")		
Release version	Changes	Date
1.0.16	Remove active parameter update to ensure compatibility with iPhone 17	2026-06-25
1.0.15	- Add BT HID barcode support. - Requires matching Atmel V2.1.22 firmware	2026-05-15
1.0.14	Add 2404MHz and 2478MHz in RF test	2025-10-09
1.0.13	Remove HID service class in normal mode.	2025-05-06
1.0.11	Fix BT reconnection problem for iOS.	2025-04-28
1.0.10	Add "Normal" HID mode. Earlier HID mode renamed to Fast HID mode	2025-04-25
1.0.9	- Add HID mode - Double click the BT button will alter the mode (normal to HID or HID to normal). - BT LED will be fast flashing in HID mode. - BT LED will be slow flashing in normal mode. - BT LED will be solid when BT is connected for both modes - RFID LED will be solid when BT is connected for HID mode without software power on.	2025-04-09
1.0.8	Fix BT button off function does not fully stop BT	2024-09-05
1.0.7	Add 2442MHz for BT test.	2024-06-11
1.0.6	Fix inventory auto stop	2023-07-07
1.0.5	Fix device name problem in C# android.	2023-06-30
1.0.4	Add BLE PER Test support.	2023-06-29
1.0.3	Fix iOS device name problem	2023-06-06
1.0.2	Initial version	2022-09-05

For CC2652R7 or R74, Initial Programming HEX Release Notes		
Release version	Changes	Date
1.0.2	Initial version	2022-10-03

RFID Firmware (from Impinj)

RFID Application: E710 RFID Firmware (from Impinj) Release Notes		
Release version	Changes	Date
2.1.2	• Latest firmware from Impinj, can only work with Atmel firmware V2.1.x; NOT compatible with Atmel firmware V0.x.x or V2.0.x • Gen2x	2025-02-19
2.1.1	• Latest firmware from Impinj, can only work with Atmel firmware V2.1.x; NOT compatible with Atmel firmware V0.x.x or V2.0.x	2024-12-03
2.1.0	• can only work with Atmel firmware V2.1.x; NOT compatible with Atmel firmware V0.x.x or V2.0.x	2024-10-22
2.0.0	• RFID Firmware from Impinj, can only work with Atmel firmware V2.0.x; NOT compatible with Atmel firmware V0.x.x	2023-09-04
1.2.0	• RFID Firmware from Impinj	2022-06-11
1.1.0	• Miscellaneous updates from Impinj	2021-12-02
1.0.0	• Initial version from Impinj	2021-09-17

PC USB App

PC USB Application: Release Notes		
Release version	Changes	Date
1.25	• Add barcode support in HID configuration.	2026-05-15
1.24	• Add RFID firmware version 2.2.x upgrade support	2025-11-18
1.23	• Add XPC1 and XPC2 support.	2025-09-05
1.22	• Add Gen2X autoset modes (5xxx) support.	2025-09-02
1.21	• Improve HID fast mode stability.	2025-06-17
1.20	• Change some text in HID configuration.	2025-06-17
1.19	• Add Impinj Gen2X rf mode. • Remove old rf mode number.	2025-05-19
1.18	• HID Mode and Normal Mode configuration • Test inventory • Upgrade Atmel, Bluetooth and RFID firmware	2025-05-19

GitHub Site for CSL Demo Apps

Please go to the following GitHub site for demo app release notes and their corresponding source codes download:

[Convergence Systems Limited · GitHub](#)