INSPECTION

HINT:

The \$RS [wire harness is integrated with the instrument hand wire harness has sembly. The wire for the \$RS wire harness have harded ube hand he had half the fornectors in the system harded yellow folor.

1. | VEHICLE NOT NVOLVED N COLLISION

Do a diagnostic system check.

(SeepageDI-386)

2. VEHICLE INVOLVED IN COLLISION

- (a) Do a diagnostic system check. (See page DI-386)
- (b) Check breaks in all wires of the SRS wire harness, and exposed conductors.
- (c) Check to see if the SRS wire harness connectors are cracked or chipped.

RS085-01