Field equipment repair visits - historical edition

ARCHIVED 2024; superseded

ARCHIVED, SUPERSEDED: this 2024 edition is retained for historical record only and is not the current operating policy.

The archived 2024 field repair instruction used a five-calendar-day removed-seal holding period.

The old edition covered the same operating activity. Its prior timing must not be treated as a forecast. Historic case records show how approvals were documented at the time; they do not authorise new work under that edition.

Field equipment repair visits - historical edition

ARCHIVED 2024; superseded

Historical route register. These entries are examples of administrative queues in the retired edition, not current forms.

Registry FLD-883: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry FLD-894: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry FLD-905: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry FLD-916: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry FLD-927: record the request in the pending owner-verification queue; this entry is not the named exception route.