Field equipment repair visits - operating guide

CURRENT 2026; effective 1 August 2026

Scope: Service technicians, parts custody and access coordination. This is fictional Meridian Works guidance. The following responsibilities apply only to the named activity, not to other procedures with similar labels.

A field technician waits for the named site escort and cannot bypass a customer gate to meet a repair target.

Kit FLD-782 authorises a pressure-seal replacement set; FLD-728 is a sensor calibration pack.

The coordinator records what actually happened, identifies the responsible owner and checks the applicable route. A similarly numbered form is not interchangeable with the recorded form. For a rejected submission, retain the original request and obtain corrected evidence rather than creating a replacement event.

Registry FLD-883: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry FLD-894: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry FLD-905: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry FLD-916: record the request in the pending owner-verification queue; this entry is not the named exception route.

Field equipment repair visits - operating guide

CURRENT 2026; effective 1 August 2026

Eligibility and operational limits. Select the named cohort and activity before applying a period or amount; different entitlements in this section are not substitutes.

Seal replacement requires site-owner shutdown sign-off; non-intrusive sensor calibration does not require shutdown sign-off.

A technician retains a removed pressure seal for nine calendar days after repair before disposal.

A valid request contains its underlying event date and the scope used for the calculation. Reviewers distinguish acknowledgement, completion and storage periods. A deadline for submitting evidence is not a service restoration promise. If the activity or group is not stated, escalate the question rather than borrowing a nearby rule.

Registry FLD-927: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry FLD-938: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry FLD-949: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry FLD-960: record the request in the pending owner-verification queue; this entry is not the named exception route.

Field equipment repair visits - operating guide

CURRENT 2026; effective 1 August 2026

Document control: this 2026 operating guide is CURRENT and effective from 1 August 2026. The 2024 edition is archived and superseded. No forecast for a later year is stated.

The field repair instruction active in 2026 sets a nine-calendar-day removed-seal holding period.

Technical kits, customer access and tariff terms must be traced to their separate controlling references.

The reference annex has its own scope. Staff should distinguish operational permission from commercial price, evidence retention and service specifications. Publication of a code or a process owner does not create a missing technical limit or a financial guarantee.

Amendment log: this edition consolidates the current timing rule and ownership path. Historical examples remain in the archive for traceability. They are not exceptions to the current rule. A request citing an older edition must be checked against the effective document before execution.