Managed router replacement - operating guide

CURRENT 2026; effective 1 August 2026

Scope: Network installers and replacement-hardware logistics. This is fictional Meridian Works guidance. The following responsibilities apply only to the named activity, not to other procedures with similar labels.

An installer validates a replacement router configuration offline before connecting the device to a live circuit.

NET-904 signals a configuration signature mismatch; NET-940 signals an unavailable time source.

The coordinator records what actually happened, identifies the responsible owner and checks the applicable route. A similarly numbered form is not interchangeable with the recorded form. For a rejected submission, retain the original request and obtain corrected evidence rather than creating a replacement event.

Registry NET-1005: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry NET-1016: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry NET-1027: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry NET-1038: record the request in the pending owner-verification queue; this entry is not the named exception route.

Managed router replacement - operating guide

CURRENT 2026; effective 1 August 2026

Eligibility and operational limits. Select the named cohort and activity before applying a period or amount; different entitlements in this section are not substitutes.

Branch-router activation is approved by the network owner; temporary event-router activation is approved by the event engineer.

A replaced router's diagnostic image is retained for seventeen calendar days after removal.

A valid request contains its underlying event date and the scope used for the calculation. Reviewers distinguish acknowledgement, completion and storage periods. A deadline for submitting evidence is not a service restoration promise. If the activity or group is not stated, escalate the question rather than borrowing a nearby rule.

Registry NET-1049: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry NET-1060: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry NET-1071: record the request in the pending owner-verification queue; this entry is not the named exception route.

Registry NET-1082: record the request in the pending owner-verification queue; this entry is not the named exception route.

Managed router replacement - operating guide

CURRENT 2026; effective 1 August 2026

Document control: this 2026 operating guide is CURRENT and effective from 1 August 2026. The 2024 edition is archived and superseded. No forecast for a later year is stated.

The network replacement procedure effective in 2026 retains diagnostic images for seventeen calendar days.

Activation approval is technical. Transit insurance belongs to logistics and cannot be inferred from network diagnostics.

The reference annex has its own scope. Staff should distinguish operational permission from commercial price, evidence retention and service specifications. Publication of a code or a process owner does not create a missing technical limit or a financial guarantee.

Amendment log: this edition consolidates the current timing rule and ownership path. Historical examples remain in the archive for traceability. They are not exceptions to the current rule. A request citing an older edition must be checked against the effective document before execution.