

TECHNICAL INSPECTION & COST ESTIMATION

Vehicle VIN: VIN1234567890ABCD

Technical Findings: Detected oil leak in the main gasket. Brake pads require urgent replacement (front pair).

Estimated Total Cost: 5000 UAH

Required Deposit: 1000 UAH

*This document is protected by a SHA-256 cryptographic hash and recorded on the blockchain ledger for integrity assurance.
Generation Date: 2026-05-11 13:43:34*