HOA Balcony Inspection Summary (SB-326) ? 2025-06-18

•	•	Type Severity Notes	
			n
	•	Structure High Joist rot suspected	
F-03	Unit 2C	Waterproofing Low Railing sealant aging	

Recommendation: Prioritize structural remediation (F-02). Waterproofing may be staged.