







Viezo sensor/servo motors:

. If you use angles servo doesn't like:

- · constant humming
- · computer loses contact Ardino (disconnect & reconnect)
- random strange errors

1. Use moderate angles $(20^{\circ} / 70^{\circ})$

2. Experiment with other combinations

(110° | 190°)

Wiring:
Brown -> GND

Red → 5 V

Orange -> Digital pin No resistor for servo

15 min. 1. (Optional) If you're almost done 15 min. 1. (Optional) If you're almost done 15 min. 25. 25 With piezo/servo code, go finish it. 2. Finish lever-show mr. Kirsch 3. Pick a partner, tell Mr. Bregar 4. Get a base and start RGM!