

Alpine Peak 2 Tent - Troubleshooting: Leaking Seams / Broken Pole

Leaking seams:

- Confirm the rainfly is fully staked and not touching the inner tent body.
- Inspect factory-taped seams for lifted tape; reseal with seam sealant if needed.
- Reapply durable water repellent (DWR) to the rainfly if water is soaking through fabric.

Broken pole section:

- Locate the included aluminum splint sleeve in the pole repair kit.
- Slide the splint over the break and secure it with the pole's shock cord tension.
- Avoid fully collapsing the pole until you can replace the damaged section.
- Contact Cairn Outdoor Co. support for a replacement pole section under warranty.