PROJECT STATUS REPORT



Export issues (No plan)

Num.	Titile	Owner - Email	Plan	Action
1	AF6CCi0071-DV-lmsg: Device init 1 time when change path make hang out traffic	nhanngt@atvn.com.vn	NONE	'Don't create a plan to fix it'
2	AF6CCl0071-Mx-DV: Need HW support tool measure BER for PDH	nhanngt@atvn.com.vn	NONE	'Don't create a plan to fix it'
4	AF6CCl0071-Mx-DV : Jitter Tolerance Function was FAILED with STM1_VC3_REMOTE	nhanngt@atvn.com.vn	NONE	'Don't create a plan to fix it'
5	AF6CCl0071_DV_DCC: Dump packet is got 2 bytes 0x00 when setup fcs16	nhanngt@atvn.com.vn	NONE	'Don't create a plan to fix it'
6	AF6CCl0071_DV_DCC: Dump packet at Rx ENCAP is incorrect (2 packets)	nhanngt@atvn.com.vn	NONE	'Don't create a plan to fix it'
7	AF6CCi0071-Mx-DV : PPP: normal path - MPEG hang out	nganpdk@atvn.com.vn	NONE	'Don't create a plan to fix it'
8	AF6CCl0071_DV_FM: FM detect alarm RAI of DS1 MUST immedialy	nhanngt@atvn.com.vn	NONE	'Don't create a plan to fix it'
9	AF6CCl0071_DV_PW: RxLbitPackets did not sync with others.	nhanngt@atvn.com.vn	NONE	'Don't create a plan to fix it'
10	AF6CCl0071_DV_Out8k: Default Eth's squelching	nhanngt@atvn.com.vn	NONE	'Don't create a plan to fix it'
11	AF6CCl0071_DV_SEM: How to reset sem uart	nhanngt@atvn.com.vn	NONE	'Don't create a plan to fix it'
12	AF6CCl0071_DV_out8k: Out8k for e-pass has not well function.	nhanngt@atvn.com.vn	NONE	'Don't create a plan

				to fix it'
13	AF6CCl0071_DV_SDK: SDK update tool check pw prbs is FAIL	nhanngt@atvn.com.vn	NONE	'Don't create a plan to fix it'
14	AF6CCl0071_DV_SDK: SDK update tool check pw speed is FAIL	nhanngt@atvn.com.vn	NONE	'Don't create a plan to fix it'
15	AF6CCl0071_DV_PW: PW unbind take long times	longdt@atvn.com.vn	NONE	'Don't create a plan to fix it'
16	AF6CCl0071_DV_ePass: Can't run full BW	nhanngt@atvn.com.vn	NONE	'Don't create a plan to fix it'
17	AF6CCl0071_DV_lmsg: encap hdlc counters, rxldleByte not count	nhanngt@atvn.com.vn	NONE	'Don't create a plan to fix it'
18	AF6CCl0071_CEM_DV_Ram_parity: Ram parity has not well function	nhanngt@atvn.com.vn	NONE	'Don't create a plan to fix it'
19	AF6CCl0071_CEM_DV_DebugTool: "debug pw speed" wrong at CLA layer	nhanngt@atvn.com.vn	NONE	'Don't create a plan to fix it'