

🔧 D400049 performed by: Calvin Waller		Type: Frequent	Date: Mar 24, 2026
Structure: Under Running Bridge - Single Girder		Description: Tx Hoist 49 3H South Cran	Customer: Wabash
Purchase Order: S2P1215028	Job #: 0270357	Location: Plant 3H North South Area	Customer Address: 500 Commerce Blvd
Manufacturer:	Serial Number:	Capacity:	Model #:
Crane: Unknown	Crane: Unk	Crane: 2.0 Ton	Crane: Unk
Hoist 1: Columbus McKinnon	Hoist 1: L314FD	Hoist 1: 2.0 Ton	Hoist 1: RR
3 Repair	26 Satisfactory Items	0 Safety and Monitor Items	4 N/A Items

🚩 Action Items 3

Under Running Bridge: Wheels

🚩 Repair 📷

Under Running Bridge: Conductors/Festoon System

🚩 Repair 📷

Hoist 1: Festoons

🚩 Repair 📷

Under Running Bridge 12/14 Satisfactory

Motors	✓ Satisfactory	Bridge Brakes	✓ Satisfactory	Control Panels	✓ Satisfactory
Wheels	🚩 Repair 📷	Disconnect Switch/Power Supply	✓ Satisfactory	Conductors/Festoon System	🚩 Repair 📷
Gear Box	✓ Satisfactory	Fluid Levels/Gaskets/Seals	✓ Satisfactory	Travel Limits/Stops	✓ Satisfactory
Rated Load Marking	✓ Satisfactory	Alignment & Tracking	✓ Satisfactory	Runway Beams/Rail	✓ Satisfactory
Bridge Girders	✓ Satisfactory	End Trucks	✓ Satisfactory		

Hoist 1 14/19 Satisfactory

Motors	✓ Satisfactory	Brakes	✓ Satisfactory	Control Panel	✓ Satisfactory
Mechanical Brake	N/A	Limit Switches/Stops	✓ Satisfactory	Gear Box	✓ Satisfactory
Fluid Levels/Gaskets/Seals	✓ Satisfactory	Upper Sheaves	N/A	Rope Drum	N/A
Lower Block	✓ Satisfactory	Rope/Chain	✓ Satisfactory	Rope/Chain Guides	✓ Satisfactory
Hook	✓ Satisfactory	Couplings	N/A	Wheels/Pinions	✓ Satisfactory
Push Button Station/Radio	✓ Satisfactory	Festoons	🚩 Repair 📷	Hoist Brake Operation	✓ Satisfactory
Clearances	✓ Satisfactory				

ACTION LIST - REPAIR ITEMS

Under Running Bridge 2 Repair items

Wheels


🚩 Repair

Note: Bearings in east wheels are bad and need to be replaced.

Conductors/Festoon System

🚩 Repair

1 / 1



Note: Does not have a ground rail

Hoist 1 1 Repair item

Festoons

Repair

1 / 3



Repair

2 / 3



Repair

3 / 3



Note: Power rail, does not have a ground rail, insulation on power bars are sliding, power bars are seperating