LOWER COLUMBIA RIVER GRP OCTOBER 2015

Bonneville Hatchery LCR-144.6L-N

Position - Location: 45° 37.993', -121° 57.462' 45° 37' 59.6", -121° 57' 27.7" 45.63321, -121.95770 Cascade Locks

Strategy Objective: Notification: Notify Bonneville Hatchery of spills that could impact their water intakes below the Bonneville Dam.

Implementation: Call ODFW Bonneville Hatchery at 541-374-8393 and inform them that a spill has occurred.

Field Notes: Hatchery is just downstream of Bonneville Dam along Tanner Creek.

Watercourse: Creek - Tanner Creek at Columba River

Resources at Risk: Fish Hatchery, Salmon - Chinook, Salmon - Coho, Steelhead, Water Intakes



Communication Process and Action:

Call ODFW Bonneville Hatchery at 541-374-8393 and inform them that a spill has occurred.

Notify the hatchery that water intakes could be impacted, and establish coordination point for incident repsonse.

APPENDIX 4B 587