



September 18, 2013

Custodian For:

Antilles At Islands At Doral

7808 NW 110th Avenue Doral, FL 33178

Presented To: Joanna Kay

Presented By: RODOLFO J SILVA Sherwin-Williams (954) 295-3972 swrep4426@sherwin.com

Custodian for

Antilles At Islands At Doral

September 18, 2013

Area Summaries

Area	Substrate	Label	Color
Main Body Color Scheme	#1 Concrete/Cement	Finish	SW 6129 Restrained Gold
Product: A80W0	151 - SuperPaint® Exterior Latex Flat Extra White	9	
Columns & Wood Fascia #	1 Other	Finish	SW 6130 Mannered Gold
Product: A80W0	151 - SuperPaint® Exterior Latex Flat Extra White	е	
Trims Color #1	Concrete/Cement	Finish	SW 6127 Ivoire
Product: A80W01151 - SuperPaint® Exterior Latex Flat Extra White			
Main Body Color Scheme	#2 Concrete/Cement	Finish	SW 6157 Favorite Tan
Product : A80W0	1151 - SuperPaint® Exterior Latex Flat		
Columns & Wood Fascia	2 Other	Finish	SW 6158 Sawdust
Product : A80W0	1151 - SuperPaint® Exterior Latex Flat Extra Whit	re	
Trims Color #2	Concrete/Cement	Primer	SW 6155 (50% lighter)
Product: A80W01151 - SuperPaint® Exterior Latex Flat			
Main Body Color Scheme	#3 Concrete/Cement	Finish	SW 6367 Viva Gold
Product : A80W0	1151 - SuperPaint® Exterior Latex Flat Extra Whit	te	

Custodian for

Antilles At Islands At Doral

September 18, 2013

Area Summaries

	Substrate	Label	Color
d Fascia #3	Other	Finish	SW 6368 Bakelite Gold
A80W01151 - SuperPaint®	Exterior Latex Flat Extra White		
	Concrete/Cement	Finish	SW 6127 Ivoire
A80W01151 - SuperPaint®	Exterior Latex Flat Extra White		
Body Color	Concrete/Cement	Finish	SW 6114 Bagel
A80W01151 - SuperPaint®	Exterior Latex Flat Extra White		
「rim A80W01151 - SuperPaint®	Concrete/Cement Exterior Latex Flat Extra White	Finish	SW 6127 Ivoire
A89W01151 - SuperPaint®	Aluminum Exterior Latex Satin Extra White	Finish	Extra White
	A80W01151 - SuperPaint® I Body Color A80W01151 - SuperPaint® rim A80W01151 - SuperPaint®	A80W01151 - SuperPaint® Exterior Latex Flat Extra White Concrete/Cement A80W01151 - SuperPaint® Exterior Latex Flat Extra White Body Color Concrete/Cement A80W01151 - SuperPaint® Exterior Latex Flat Extra White Concrete/Cement A80W01151 - SuperPaint® Exterior Latex Flat Extra White	ABOW01151 - SuperPaint® Exterior Latex Flat Extra White Concrete/Cement Finish ABOW01151 - SuperPaint® Exterior Latex Flat Extra White Body Color Concrete/Cement Finish ABOW01151 - SuperPaint® Exterior Latex Flat Extra White Tim Concrete/Cement Finish ABOW01151 - SuperPaint® Exterior Latex Flat Extra White Aluminum Finish

Custodian for

Antilles At Islands At Doral

September 18, 2013

Area Detail

Area:	Main Body Color Scheme #1		
Substrate:	Concrete/Cement		
Label:	Finish		
Color:	SW 6129 Restrained Gold		
Product:	A80W01151 - SuperPaint® Exterior Latex Flat Extra White		
This Product is available at this Sherwin V	Villiams location:	Sherwin-Williams Store # 2644 MIRAMAR 11820 MIRAMAR PKWY BLDG 6 MIRAMAR, FL 33025 (954) 436-6511	

Additional Comments:

UNT#

10745-10709;8131-8081;7831-7801;10737-10773;7845-8065;7808-7848;10831-10801;8183-8123;8125-8165;10809-10845; 10829-10849;8080-8140;10880-10850; Continues in next line for Scheme #1



Custodian for

Antilles At Islands At Doral

September 18, 2013

Area Detail

Area:	Columns & Wood Fascia #1		
Substrate:	Other		
Label:	Finish		
Color:	SW 6130 Mannered Gold		
Product:	A80W01151 - SuperPaint® Exterior Latex Flat Extra White		
This Product is available at this Sherwin Williams location:		Sherwin-Williams Store # 2644 MIRAMAR 11820 MIRAMAR PKWY BLDG 6 MIRAMAR, FL 33025 (954) 436-6511	

Additional Comments:

This is the color for columns & wood fascia for the "First Scheme". UN#'s 7880-7840; 10874-10894; 10901-10925; 7808-7840; 7847-7885; 10955-10931



Custodian for

Antilles At Islands At Doral

September 18, 2013

Area Detail

Area:	Trims Color #1	
Substrate:	Concrete/Cement	
Label:	Finish	
Color:	SW 6127 Ivoire	
Product:	A80W01151 - SuperPaint® Exterior Latex Flat Extra White	
This Product is available at this Sherwin Williams location:		Sherwin-Williams Store # 2644 MIRAMAR 11820 MIRAMAR PKWY BLDG 6 MIRAMAR, FL 33025 (954) 436-6511

Scheme #1 Trim Color

SW 6127 Ivoire

Additional Comments:

Custodian for

Antilles At Islands At Doral

September 18, 2013

Area Detail

Area:	Main Body Color Scheme #2	Main Body Color Scheme #2		
Substrate:	Concrete/Cement	Concrete/Cement		
Label:	Finish	Finish		
Color:	SW 6157 Favorite Tan	SW 6157 Favorite Tan		
Product:	A80W01151 - SuperPaint® Exterior Latex Flat			
This Product is available at this Sherw	vin Williams location:	Sherwin-Williams Store # 2644 MIRAMAR 11820 MIRAMAR PKWY BLDG 6 MIRAMAR, FL 33025 (954) 436-6511	_	

Additional Comments:

 $\label{loss} Unit\# s \ 10793-10751; 8172-8122; 8061-7911; 10718-10748; 10800-10830; 8048-8108; 10799-10769; \\ 10774-10738; 10802-10832; 8167-8127; 7920-8070; 8121-8157; 10850-10870; 10900-10936; 7806-7838; 7885-7835$



Custodian for

Antilles At Islands At Doral

September 18, 2013

Area Detail

	• 000 000 10 000 100 000 000 000 000 000	Columns & Wood Fascia #2	
Other			
Finish	Finish		
SW 6158 Sawdust	SW 6158 Sawdust		
A80W01151 - SuperPaint® E	A80W01151 - SuperPaint® Exterior Latex Flat Extra White		
erwin Williams location:	Sherwin-Williams Store # 2644 MIRAMAR		
	11820 MIRAMAR PKWY BLDG 6 MIRAMAR, FL 33025 (954) 436-6511		
	Finish SW 6158 Sawdust	Finish SW 6158 Sawdust A80W01151 - SuperPaint® Exterior Latex Flat Extra White erwin Williams location: Sherwin-Williams Store # 2644 MIRAMAR 11820 MIRAMAR PKWY BLDG 6 MIRAMAR, FL 33025	

Additional Comments:

This is the column and wood fascia color for "Scheme #2" Unit#'s 7848-7886; 10983-10959; 10927-10903; 10896-10860



Custodian for

Antilles At Islands At Doral

September 18, 2013

Area Detail

Area:	Trims Color #2	
Substrate:	Concrete/Cement	
Label:	Primer	
Color:	SW 6155 (50% lighter)	
Product:	A80W01151 - SuperPaint® Exterior Latex Flat	
This Product is available at this Sherwin W	filliams location:	Sherwin-Williams Store # 2644 MIRAMAR 11820 MIRAMAR PKWY BLDG 6 MIRAMAR, FL 33025 (954) 436-6511

Additional Comments:

This is the trim color for "Color Scheme #2".
****This is color# SW6155 has to be made 50% lighter*****

SW 6155 Rice Grain *MAKE SURE TU REQUEST THIS color to be made 50-1. lighter #

Custodian for

Antilles At Islands At Doral

September 18, 2013

Area Detail

Area:	Main Body Color Scheme #3	
Substrate:	Concrete/Cement	
Label:	Finish	
Color:	SW 6367 Viva Gold	
Product:	A80W01151 - SuperPaint® Exterior Latex Flat Extra White	
This Product is available at this Sherwin V	Villiams location:	Sherwin-Williams Store # 2644 MIRAMAR 11820 MIRAMAR PKWY BLDG 6 MIRAMAR, FL 33025 (954) 436-6511

Additional Comments:

This color is for the main body color for "Scheme #3".
Unit#'s 10798-10768; 8191-8141;8062-7852; 10754-10784; 10745-10715; 8154-8124; 8126-8166; 8178-8118; 10824-10848; 8039-8109; 8146-8188;



Custodian for

Antilles At Islands At Doral

September 18, 2013

Area Detail

Area:	Columns & Wood Fascia #3	
Substrate:	Other	
Label:	Finish	
Color:	SW 6368 Bakelite Gold	
Product:	A80W01151 - SuperPaint® Exterior Latex Flat Extra White	
This Product is available at this Sherwin Williams location:		Sherwin-Williams Store # 2644 MIRAMAR 11820 MIRAMAR PKWY BLDG 6 MIRAMAR, FL 33025 (954) 436-6511

Additional Comments:

This color is for the columns & wood fascia for "Scheme #3"

Unit#'s 10839-10851; 7849-7819; 10863-10895; 10942-10984; 7846-7884; 7807-7839; 10918-10902; 10893-10861



Custodian for

Antilles At Islands At Doral


September 18, 2013

Area Detail

Area:	Trims Color #3	
Substrate:	Concrete/Cement	
Label:	Finish	
Color:	SW 6127 Ivoire	
Product:	A80W01151 - SuperPaint® Exterior Latex Flat Extra White	
This Product is available at this Sherwin V	Villiams location:	Sherwin-Williams Store # 2644 MIRAMAR 11820 MIRAMAR PKWY BLDG 6 MIRAMAR, FL 33025 (954) 436-6511

Additional Comments:

This color is for the trims in both "Scheme #1 & Scheme #3"



Custodian for

Antilles At Islands At Doral

September 18, 2013

Area Detail

Area:	Entrance Walls Body Color	
Substrate:	Concrete/Cement	
Label:	Finish	
Color:	SW 6114 Bagel	
Product:	A80W01151 - SuperPaint® Exterior Latex Flat Extra White	
This Product is available at this Sherwin Williams location:		Sherwin-Williams Store # 2644 MIRAMAR 11820 MIRAMAR PKWY BLDG 6 MIRAMAR, FL 33025 (954) 436-6511

Additional Comments:

This color is for main body color at all the Entrance walls of the association.



Custodian for

Antilles At Islands At Doral

September 18, 2013

Area Detail

Area:	Entrance Walls Trim		
Substrate:	Concrete/Cement		
Label:	Finish		
Color:	SW 6127 Ivoire		
Product:	A80W01151 - SuperPaint® Exterior Latex Flat Extra White		
This Product is available at this Sherwin Williams location:		Sherwin-Williams Store # 2644 MIRAMAR 11820 MIRAMAR PKWY BLDG 6 MIRAMAR, FL 33025 (954) 436-6511	

This color is for al the trims of the Entrance walls to the association.

SW 6127 Ivoire

Additional Comments:

Custodian for

Antilles At Islands At Doral

September 18, 2013

Area Detail

Area:	Doors		
Substrate:	Aluminum		
Label:	Finish		
Color:	Extra White		
Product:	A89W01151 - SuperPaint® Exterior Latex Satin Extra White		
This Product is available at this Sherwin Williams location:		Sherwin-Williams Store # 2644 MIRAMAR 11820 MIRAMAR PKWY BLDG 6 MIRAMAR, FL 33025 (954) 436-6511	

Our Extra White color is for all the doors.

Additional Comments:

Page 15





Reference Pages



Care and Cleaning of Interior and Exterior Coatings

The Sherwin-Williams Company Cleaning Products

DeckScapesTM Deck Wash is designed to bring back the fresh, natural look of your deck. Enjoy the self-working, no scrub formulation. This product is an excellent choice to restore your surface or to use as a pretreatment for staining, preserving, or sealing. Use on decks and outdoor furniture made of pressure treated wood, cedar, pine, and most other woods. This product is intended for exterior use only.

DeckScapesTM Stain & Sealer Remover is specifically designed to remove most semi-transparent and weathered solid latex and oil-based stains from decks and other exterior wood. DeckScapes Stain & Sealer Remover allows you to change the color of your deck or siding by restoring the natural beauty of the wood. DeckScapes Stain & Sealer Remover can be used on all exterior wood surfaces such as decks, siding and fences and will remove the following stains and finishes:

- · Polyurethane and some weathered latex paint.
- · Oil-based toners, semi-transparent, and weathered solid stains.
- · Water-based toners, semi-transparent, and weathered stain.
- · Water-reducible toners, semi-transparent and weathered solid stains.
- Old, weathered, clear protective finishes.

DeckScapes Stain & Sealer Remover will restore color to severely weathered and discolored wood.

DeckScapesTM Revive® Deck & Siding Brightener is a fast-acting, ready-to-use cleaner specially formulated for cedar, redwood and other highly resinous exterior woods as well as dense woods such as mahogany. Due to the chemical characteristics of these types of woods, traditional cleaners can leave the surface with an unnatural, darkened appearance. DeckScapes Revive Deck & Siding Brightener will help remove dirt and unsightly stains caused by mildew and algae, gray and weathered wood, tannin bleed and nail bleed as well as stubborn mill glaze (a surface barrier to wood coatings found on most newly installed cedar and redwood) and restore the surface to its bright, clean natural look. DeckScapes Revive Deck & Siding Brightener can be used on any new or existing exterior structure including wood decks, fences, siding, shakes, shingles, boat docks, boardwalks, outdoor furniture, picnic tables, hot tubs, planters, benches, trellises and gazebos.

H&C Concrete Etching Solution is a phosphoric acid-based etcher that has been developed to acid etch concrete surfaces before applying H&C Silicone Acrylic Concrete Sealer, H&C Shield Plus Concrete Stain, and other coatings Uses: • Basement floors and walls • Garage floors, carports and driveways • Porches, patios, walkways, steps • Swimming pool aprons • Recreation areas • Parking structures and parking lots • Retaining walls • Containment areas • Tilt-up construction • Removes efflorescence (alkali salts) • Reduces the pH of new concrete and new mortar joints.

H&C Degreaser is a concentrated heavy-duty cleaner that will remove most automotive fluids (oil, grease, brake fluid, transmission fluid, gear fluid and antifreeze) from concrete and masonry surfaces. Its primary use is to degrease and prepare concrete, block, brick, and masonry. Features: • Removes grease and oil stains • Prepares surfaces for paints, stains, and sealers • Increases any coating's ability to bond with the surface by providing a clean substrate Recommended Uses: • Stadium Supports • Bridges and Bridge Structures • Parking Garages • Patios and Walkways • Pool Decks • Concrete Driveways • Garage Floors • Block & Stucco Walls • Athletic/Tennis/Shuffleboard Courts • Other Concrete Surfaces • Use prior to etching



BASICS OF TOUCH-UP

Often a painted area needs repair. Usually the damaged area is small and is repaired using a brush and roller. The art of repair is called "touching up" and there are many problems in making the repair as invisible as possible. Prerequisites for achieving good "touch-up" are that the paint be of the same color as the original, from the same manufacturer, from the same batch of paint and, ideally, from the same can, and that the area to be repaired has the same texture and appearance of the surrounding area. If the "touch-up" patch is visible under all illumination conditions then it is poorly done; if one must search for it, then the "touch-up" is good.

COMPONENTS OF "TOUCH-UP"

Touch-up complaints are often not specific about what aspect makes the repair visible. In fact, there are three separate and identifiable components that can be included in a "touch-up" problem. All three components contribute to the visibility of the repair and stem from the use of different application techniques for the original paint and the repair. Usually a brush repair over an airless sprayed original will be very visible. Most of the following comments concern that situation, but they can also be applied to other combinations. On some jobs one problem may be visible, on others they may occur in combinations. It is much easier to understand the cause of the poor "touch-up" if the problem components are identified. 1. "HALO"

Halo's are created at the edge of the repair by tendrils of paint left by the brush as it enters and exits the area around the patch. Human eyes are very good at determining texture changes and are thus very sensitive to touch-up and "halo" in particular. The texture is more raised in these areas than the main part of the repair, so they produce shadows when illuminated from the far side and reflect light back to the observer when illuminated from the same side.

A painter can make the situation worse by attempting to feather the repair excessively. This creates more edge texture. Halo is diminished if the paint spreads smoothly and continuously over the original layer. If the repair paint thickens in viscosity rapidly as it is spread then it will not level well and the texture at the edge will be especially bad. Thus patching over porous paint, e.g. a flat paint, is more likely to cause a "halo" problem. In the field the "halo" problem may be alleviated by stippling with a brush or otherwise trying to duplicate the texture of the original. Diluting the repair paint by 10-15% may help by accommodating the wicking problem.

2. DIFFERENT SHEEN

This part of the "touch up" problem is noticed as a difference over the whole repair patch particularly at oblique angles. The patch appears either shiny or dull compared to the background. The effect may be accompanied by a "halo".

Features larger than three mil, e.g. brush marks, roller stipple etc., produce shadowing or reflections like the "halo", but not a change in sheen. Sheen differences are due to changes in the way the light is scattered from smaller features, i.e., roughness, in the paint surface. The shape and the arrangement of the paint ingredients are what determine this. Changes in surface roughness are most visible at grazing angles of observation and illumination. This is often the way that poor touch-ups are first noticed. Drying conditions and application technique are important factors in determining surface roughness. Although paint can be formulated to minimize their importance, sheen differences may be seen when the original paint and the repair paint are applied differently or under widely different temperature and/or humidity conditions.

3. COLOR DEVELOPMENT

This problem is much less likely to occur than the other two types of touch-up problem. It most often appears as a difference in the depth of the color rather than a color shift, and can be seen at almost any angle of observation, but particularly near the perpendicular (90° angle) in contrast to the "halo" and "sheen" components above.

Changes in the way light is scattered from within the body of the paint film are most visible straight on for both observation and illumination. Poor color touch-up results from differences in pigment particle separation caused by the differences in application techniques, e.g. brush vs. airless spray. Airless spraying inputs a very great deal of energy into paint and disperses pigment very well. Brushing or rolling shearrates are two to three orders of magnitude less severe and may not disperse paint components in the same way.

Reprinted from The Sherwin-Williams Materials Science R&D 1991, edited August 2008