Symptom:
ACM MESSAGE NOT REC'D BY MIC

When Monitored and Set Condition:

ACM MESSAGE NOT REC'D BY MIC

When Monitored: With the ignition in the Run/Start position, Instrument Cluster in power-up state.

Set Condition: The Instrument Cluster detects loss of communication with the Air Bag Control Module (ACM).

POSSIBLE CAUSES
ACM MESSAGE NOT RECEIVED

TEST	ACTION	APPLICABILITY
1	Turn the ignition on. **NOTE: Ensure the Instrument Cluster communicates on the PCI Bus.** With the DRBIII®, select Body, Electro/Mech Cluster, then read DTCs. Does the DRBIII® display ACM Message Not Rec'd by MIC? Yes → Refer to the COMMUNICATION category and perform the appropriate symptom. Perform BODY VERIFICATION TEST - VER 1. No → Test Complete.	All