Laser_Power_Off_Test

September 2, 2017

1 Laser Power Off Test

1.1 Object

- Figure out at what voltage the laser resets the MCU

2 Code:

```
In [1]: import GCode
        import GRBL
        cnc = GRBL.GRBL(port="/dev/cnc_3018")

        print("Laser Mode: {}".format(cnc.laser_mode))

Laser Mode: None
```

2.1 Test Setup

Power Supply: - CicuitSpecialists CSI3010SW
    Position the paper & other things.

```
In [2]: import numpy as np

In [3]: def laser_on(pwm):
            if int(pwm) != np.uint8(pwm):
                raise(Exception("UINT8! {}".format(pwm)))
            # Set minimal power setting to focus and position laser
            cnc.cmd("M3 S{:03d}".format(np.uint8(pwm)))
            cnc.cmd("G1 F10") # Laser On

        def laser_off():
            cnc.cmd("M5") # Laser off

In [4]: laser_on(255)
```

- ~18 volts.