Inspection Report

Luxury Downtown Apartment | New York, NY

Document control	RC-1-INSP / SCENARIO v1.0
Prepared / model date	October 16, 2026
Status	SAMPLE - FICTIONAL / NOT VERIFIED

FICTIONAL DESKTOP SCENARIO - NO SITE VISIT PERFORMED

Prepared for the sample investor vault. All conditions, observations, and repair budgets below are invented to demonstrate reporting format. No inspector attended the property, tested equipment, or issued a professional opinion.

Inspection profile	Scenario scope
Property configuration	1 x 3BR / 2BA condo, 1,800 sq ft
Scenario date / method	October 16, 2026 / fictional visual inspection scenario
Inspector / license	No inspector engaged; no license or certification represented
Access / weather / occupancy	Not observed; no access, weather, or occupant interview records
Records available	Catalog description only; no plans, service logs, surveys, or inspection photographs

Executive summary

This scenario contains 3 repair or investigation items: one high-priority item and two medium-priority items. The high-priority item would need prompt qualified review if present in reality. This sample is not a statement of habitability, code compliance, structural adequacy, or suitability for purchase.

System / area	Scenario review status
Structure / foundations	Not assessed; specialist review required for actual conclusions
Roof / exterior / drainage	Visible-condition example only; concealed components excluded
Electrical / plumbing / HVAC	No operational, safety, or performance testing performed
Environmental / accessibility	Asbestos, lead, mold, radon, flood risk, and accessibility not evaluated

Findings & action register

Fictional findings and budget allowances - not contractor quotations.

Item / priority	Illustrative observation and recommended action	Budget range
01. Electrical High	Open junction cover in utility cupboard; isolate access and have an electrician inspect.	$350 - $800
02. Wet areas Medium	Discolored sealant at shower tray; renew seals and check for concealed moisture.	$400 - $950
03. HVAC Medium	Service records unavailable; service fan-coil units and verify condensate drainage.	$500 - $1,100

Priority and follow-up

High: if verified, address access or safety exposure promptly and obtain an appropriately qualified assessment. Medium: obtain a written scope and quote before scheduling planned repairs. Timing here is illustrative and does not replace statutory requirements, emergency procedures, or agreement deadlines.

Budget and exclusions

The aggregate sample allowance is $1,250 to $2,850, before taxes, permits, specialist design, concealed defects, and contingency. These invented allowances are not market quotes and are not included as a separate capital expenditure line in the financial projection. Approved work may require additional funding.

Governance and work responsibility

The SPV should coordinate review under the DAO agreement, obtain evidence, and assign authorized property work to the owner or an appointed service provider. The actual responsible party and deadlines must follow the executed agreement. A ticket records assignment and progress; it does not verify the condition or certify the repair.

Limitations and completion evidence

A real inspection should identify its scope, inspector credentials, access restrictions, photographs, testing methods, and applicable standards. Obtain licensed specialist reports where appropriate. Completion should be supported by invoices, photographs, test results, permits, and a follow-up assessment as needed. This sample has no signature or professional certification.

SAMPLE ONLY