

RMU INSPECTION REPORT

BANGALORE ELECTRICITY SUPPLY COMPANY LIMITED

O/o. The General Manager (Ele.), DAS & Smart Grid, BESCOM, BICC-1 Bldg, 2nd Sector, 24th Main, 17th Cross, HSR layout, Bangalore – 560102

Basic Information

Site Code	5W1792	Circle	SOUTH
Division	Jayanagar	Sub-Division	S14
O&M	J P Nagar	Feeder Number & Name	Megha Darshini RMU
Inspection Date	01/01/45959	RMU Make/Type	C.G.L 5 way
Location/HRN	Vijaya wheel RMU	Serial No	991231
Lat & Long	12.906168 77.591855	C/o Feeder Name	F19 Sarakki MUSS

Additional Details

Previous AMC Date	01/01/45702	MFM Make	EAPL EMS-01
Relay Make & Model No	CGL14C	FPI Make & Model No	CGL31
RTU Make & SIno	CGL/C321131171490		

RMU Status & Conditions

RMU Status	Working	24V Availability	YES
PT Voltage (110V) Availability	YES	Battery Charger Condition	Faulty
Earthing Connection	Good	Comm. Accessories Availability	Available
FPI Status	Good	12V Availability	YES

Overall Wiring Issue	YES	Control Card	Faulty
Bedding Condition	Damaged	Battery Status	Not Available
230V Availability	YES	SF6 Gas	Green
RMU Location Same as GIS	YES	Door Hydraulics	Faulty
Control Cabinet Door	Damaged	Door Gasket	Damaged
Dummy Latch Command	Not Working		

Terminal Details (Fields 21-61)

Parameter	OD1	OD2	VL1	VL2	VL3
Cables Connected	YES	YES	YES	NO	YES
Connected To	O/G	I/C	Load	Idle	Load
Load Amps (R)	74.11	101.13	0		
Load Amps (Y)	75.17	101.83	0		
Load Amps (B)	75.51	106.37	0		
Switch Position	Close	Close	Close	Close	Close
ON/OFF Motors	Removed	YES	YES	Removed	YES
Breaker Status	Charged	Charged	Charged	Charged	Charged
Cable Entry Doors	Damage	Damage	Damage	Damage	Damage
Local/Remote Switch	Good	Good	Good	Good	Good
VPIS Indication	Good	Good	Good	Faulty	Good
MFM Working	Good	Good			
Relay Working			Good	Faulty	Faulty
RMU Side 24 Pin	YES	YES	YES	YES	YES

Parameter	OD1	OD2	VL1	VL2	VL3
Cable IC From or OG To	Megha Darshini RMU	F19 Sarakki MUSS	S14 HT-13 M S Building	Milk Booth DTC-72	M S Building DTC-325

Additional Information

Remarks/Issues	1.Control card & 1 no 24v SMPS faulty 2.Relay VL2& VL3 wiring issue 2.OD1&VL2 motors have removed are not intact not suitable for remote operation 3. 3 Nos of 12v Batteries are not at site. CC & Cable entry doors are damaged.4.VL2 kept idle ,VL3 connected to 2 cables VL2 is connected to VL3.
----------------	--

Generated on 16/12/2025, 1:08:05 pm

BESCOM - Distribution Automation System