


Revision 05.04.20



#### IN GND SW OUT

#### Controls

- Boost
- Tone



## **Lenora Boost**

Parts List

RESISTORS (1/4W)		
R1	10K	
R2	1M	
R3	100K	
R4	560R	
R5	5K1	
R6	10K	
R7	1K5	
R8	1K5	
R9	1K	
R10	2K	
R11	15K	
R12	422K	
R13	1K	
R14	4K7	
R15	22K	
R16	47K	
R17	27K	
R18	12K	
R19	15K	
R20	392K	
R21	1K8	
R22	100K	
R23	4K7	
R24	100K	
R25	560R	

68K

68K

100K

27K

27K

3K3

100K

100K

3K3

R26

R27

R28

R29

R30

R31


R32

R33

R34

CAPA	CITORS
C1	100n
C2	47u
C3	100n
C4	390n
C5	68n
C6	1u
C7	68n
C8	27n
C9	2n2
C10	1u
C11	1u
C12	390p
C13	82n
C14	820p
C15	3n9
C16	4u7
C17	4u7
C18	47u
C19	1u
C20	1u
C21	1u
C22	1u

_	·	
	INTEGRA	TED CIRCUITS
	IC1	TL072
	IC2	TL072
	IC3	TC1044SCPA
	<b>DIODES</b>	
	D1	1N5817
	D2	SH270
	D3	SH270
	D4	1N4001
	D5	1N4001
	POTENTI	OMETERS
	BOOST	B10K
	TONE	B10K





### **Lenora Boost**

Wiring Diagram





# Lenora Boost Drill Template 125B Enclosure

