


Contact: Gavin Lean
Company: Bowpall Pty Ltd T/A Advanced Roof Tiling Lic No: 155412C
Phone: 0403747730
Email: gavlean@hotmail.com

Created: Tue 07 July 08:03 2026
Location: 381 Reddall Parade Mount Warrigal
Title: Roof Report # S67771=SP=01
No. Items: 10

This report has been produced to facilitate claim resolution, is unbiased and objective, and is based on the information available at the time of writing.



7896.jpeg

Created: Tue 07 July 08:03 2026

I inspected the single storey concrete tile roof which is approximately 33 years old with a roof pitch of approximately 18° and is in good condition for its age.

I inspected the area over garage ceiling after NBN contractors accessed internal roof space via man hole in garage.

☆No harness required as I have inspected roof area over garage via internal man hole☆



7897.jpeg

Created: Tue 07 July 08:08 2026

Arrow's show gyprock joint which has separated.

Contact: Gavin Lean
Company: Bowpall Pty Ltd T/A Advanced Roof Tiling Lic No: 155412C
Phone: 0403747730
Email: gavlean@hotmail.com

Created: Tue 07 July 08:03 2026
Location: 381 Reddall Parade Mount Warrigal
Title: Roof Report # S67771=SP=01
No. Items: 10

(3)



7898.jpeg

Created: Tue 07 July 08:10 2026

Arrow show's gyprock joint which has separated.

(4)



7899.jpeg

Created: Tue 07 July 08:10 2026

Arrow show's the gyprock sagging between trusses. Gyprock fixings are intact.

Contact: Gavin Lean
Company: Bowpall Pty Ltd T/A Advanced Roof Tiling Lic No: 155412C
Phone: 0403747730
Email: gavlean@hotmail.com

Created: Tue 07 July 08:03 2026
Location: 381 Reddall Parade Mount Warrigal
Title: Roof Report # S67771=SP=01
No. Items: 10

(5)




7900.jpeg

Created: Tue 07 July 08:13 2026

There is no evidence of water ingress into roof space over garage ceiling.

(6)



7901.jpeg

Created: Tue 07 July 08:14 2026

Owner has previously repaired gyprock ceiling in garage.

Contact: Gavin Lean
Company: Bowpall Pty Ltd T/A Advanced Roof Tiling Lic No: 155412C
Phone: 0403747730
Email: gavlean@hotmail.com

Created: Tue 07 July 08:03 2026
Location: 381 Reddall Parade Mount Warrigal
Title: Roof Report # S67771=SP=01
No. Items: 10

(7)



7902.jpeg

Created: Tue 07 July 08:15 2026

No broken tiles noted over garage ceiling.

(8)



7903.jpeg

Created: Tue 07 July 08:15 2026

Owner has installed solar approximately 3 years ago over garage ceiling by contractors.

Contact: Gavin Lean
Company: Bowpall Pty Ltd T/A Advanced Roof Tiling Lic No: 155412C
Phone: 0403747730
Email: gavlean@hotmail.com

Created: Tue 07 July 08:03 2026
Location: 381 Reddall Parade Mount Warrigal
Title: Roof Report # S67771=SP=01
No. Items: 10

(9)



7904.jpeg

Created: Tue 07 July 08:17 2026

Photo show's broken watercourse under solar panels over garage ceiling.

(10)



7905.jpeg

Created: Tue 07 July 08:18 2026

Photo show's broken watercourse under solar panel over garage ceiling.

Contact: Gavin Lean
Company: Bowpall Pty Ltd T/A Advanced Roof Tiling Lic No:
155412C
Phone: 0403747730
Email: gavlean@hotmail.com

Created: Tue 07 July 08:03 2026
Location: 381 Reddall Parade Mount Warrigal
Title: Roof Report # S67771=SP=01
No. Items: 10

CONCLUSION: In my opinion separation between gyprock ceiling sheets is due to glue failure and not due to water ingress.

This is a maintenance issue and not storm related or due to NBN installation.