1 POTENTIOMETER AS ANGLE SENSOR

1.1 Tasks:

1. Add the potentiometer to the shaft of barrier gate.



Slika 1: Adding potenciometer as an angle sensor.

2. Test the potentiometer values with next program:

```
void setup() {
 Serial.begin(9600);
}

void loop() {
 Serial.println(analogRead(A3));
 delay(100);
}
```

3. Change the functions for lifting and lowering the barrier gate to use potenciometer readings instead of switch and time controlled movement.

```
        [+] void setup() {
        [+] void loop() {
        [+] void manualControll(){
```

```
        [+] void gateStop(){
        [-] void gateUp() {
    while (analogRead(A3) < 750){            digitalWrite(7, HIGH);
         digitalWrite(6, LOW);
         }
         gateStop();
        }
        [+] void gateDown() {
```

1.2 Questions:

1. What is the value of the angle sensor when the barrier gate is in the upper orientation...
2. ... and in lower orientation.

1.3 Summary:

1.3.1 <++>

<++>

1.4 Issues:

1.4.1 <++>

<++>