

From: East Gippsland Building Surveyors P/L <malcolm@egbs.com.au>
Sent: Wednesday, July 5, 2017 2:02 PM
To: Dean
Subject: Re: implications check first: 9 OUTLOOK AVE, LAKES CLIENT: Home Stump Holes, all 21 dug out. Online visual check all ready BEFORE onsite inspection.

Hi Dean,

The implications for you are that you will need to find another building surveyor to replace me, which may be difficult locally as there is only one, the next stop would be Traralgon which has several.

I have no idea what the new BS would want to charge you, for inspections etc.

I do understand that the "terminations" dept. of the VBA is very busy, so there would be a delay in changing over (but not by me)

Kind regards,

Malcolm



Malcolm Findlay
Building Surveyor BSL 33560
East Gippsland Building Surveyors P/L
P.O. Box 889
Bairnsdale
Ph. 0438564141

On 5/07/2017 1:41 PM, Dean Leonard wrote:

(Wednesday 5-Jul-2017 1:36:21 PM)

Thank you Malcolm,

That is best for all.

Before I do that, what are the implications that can disrupt my project budget or situation? A synopsis only, as you would know the process by heart, and it will take you a few seconds to type. I have lost enough time with this, and do not want to get through hours of a form, just to find some influential factor.

I.e. No implications.

After this measly easy quick request, if no implications, we will never speak or communicate again...

Dean
Database Design & Development

JWARE Australia

Mail: jware-ceo@outlook.com
Phone: +61 423 386 744

COMMUNICATION CLOUD

ABN: 2XXXX9 • Victoria • Australia

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. The integrity and security of this message cannot be guaranteed on the Internet UNLESS we encrypt our correspondence, which will be done on request or JWare considers it so.

From: East Gippsland Building Surveyors P/L [<mailto:malcolm@egbs.com.au>]

Sent: Wednesday, 5 July 2017 9:20 AM


To: Dean

Subject: Re: 9 OUTLOOK AVE, LAKES CLIENT: Home Stump Holes, all 21 dug out. Online visual check all ready BEFORE onsite inspection.

Hi Dean,

See attached information sheet on how to terminate my services.

I will have no objection to you moving to another Building Surveyor, so please send your request to the VBA



On 4/07/2017 5:30 PM, Dean wrote:

Can i be released from your services? VBA said you decide? That would be better for all.

Sent from my Samsung Galaxy smartphone.

----- Original message -----

From: East Gippsland Building Surveyors P/L

Date: 4/07/2017 4:25 PM (GMT+10:00)


To: Dean

Subject: Re: 9 OUTLOOK AVE, LAKES CLIENT: Home Stump Holes, all 21 dug out. Online visual check all ready BEFORE onsite inspection.

I am able to work with you as long as you follow the rules, that is you phone the office (not me) when YOU are ready for an inspection giving 24 hours notice.

Your the builder, you are totally responsible for the construction.

If you wish to change to another building surveyor thats fine by me, just contact the Building Authority, and they will help you through the process.



On 4/07/2017 1:32 PM, Dean wrote:

Tone it down a bit Malcolm. I provide optional logical electronic information to match modern companies.

If you don't want to optionally look at it then don't. Simple. No need for antagonistic prods.

If you don't want to do business with me, tell me now and we will cease contact, else if not I expect done normal business respectful manner.

Because my budget had been destroyed by my gone supplier giving wrong info in email that caused an 8 month delay and huge motel costs, and working hard getting the project back on track. I have to get concrete quotes first to see if I can handle the costs, then of course your inspection preceding that.

Will await your response to see if you want to work with me as a business contact or not?

In the interim I will complete the cross over application.

Dj

Sent from my Samsung Galaxy smartphone.

----- Original message -----

From: Malcolm Findlay

Date: 3/07/2017 6:56 PM (GMT+10:00)

To: Dean

Subject: Re: 9 OUTLOOK AVE, LAKES CLIENT: Home Stump Holes, all 21 dug out. Online visual check all ready BEFORE onsite inspection.

YOU must book an inspection by phoning the office on 0458564141 so that an inspection of the holes can be made, IF you ignore this advice your permit will receive a STOP Work notice

PHotos are NOT acceptable and never have been, you may be an IT expert but that does not meet the requirements of the VBA.

AS previously advised do NOT email me further, they will not be answered.

Kind Regards.

Malcolm

On 3 Jul 2017, at 4:50 pm, Dean

<da.vinci.place@outlook.com> wrote:

(Monday 3-Jul-2017 4:16:57 PM)

Good Afternoon Malcolm,

As discussed, yesterday after much hard but satisfying work, I have dug out with whatever tools and implements I could muster, and finally have completed all 21 holes.

- All holes have a carpet absorbent intimate join (serving as a sponge and a barrier) laid across them, preventing any water flow of a horizontal trajectory, into the holes.

- All holes have a trenches and / or dirt walls around them, preventing any water flow of a horizontal trajectory, into the holes.
- All holes have a wood and / or plastic above them, preventing any water flow of a vertical trajectory (rain), into the holes.
- My existing drainage system I built a year ago that stops the former water flow across my home site is set up and doing the job perfectly to this day.
- All holes easily encompass with excess coverage, the minimum home supplier and soil tester joint structural requirements of 45 cm diameter x 90 cm's depths for the 21 holes.
- All holes when dug out hit or arrived at the DRY CLAY soil base. Even those on the north wall that are in proximity to underground superficial water flow and seepage (which no-one can stop)
- All of the above mean apart from the moisture in the air, NO WATER GETS INTO ANY OF THE HOLES even in a torrential downpour.

Click on any of the links below to download the single file in the top level of this Web Cloud. It's too big to email.

It has already been opened by several of my home supplier contacts so it works OK.

However if you have any problems I will make a custom web page of it for you.

https://1drv.ms/f/s!Atc5DTOu_W2pgssiBLkQZO5Pm2pzow

Alternatively, the same link is in my signature block below;

[COMMUNICATION CLOUD](#)

*View it online if you want, and if you want the pdf on your own computer, select the file, then click download in the cloud window.

When you are satisfied with the visuals of the holes without the expense of an actual visit, then at your convenience, email me the process we follow for your VBA approved visits, and then I can make an appointment for you to see my property for your inspection. In the interim, I will now complete the crossover form as required by Lachlan before your visit.

Await your next instruction...

Dean

Australia

Mail: jware-ceo@outlook.com

SMS: +61 423 386 744

ABN: 2XXX9 • Victoria • Australia

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. The integrity and security of this message cannot be guaranteed on the Internet UNLESS we encrypt our correspondence, which will be done on request or JW are considers it so.