

				i (Ŧ)
Prepared (also subject responsible if other)		No.		
Rajasekar R				
Approved	Checked	Date	Rev	Reference
		27-03-2020	Ver1.0	

## **MOP of PLA Down Alarm for Huawei Site**

#### **Table of contents**

Activity Description	2
Flow Chart	
Activity Details	
activity Details	4



ERICSSON 🗲 2 (4)

Prepared (also subject responsible if other)		No.		
Rajasekar R				
Approved	Checked	Date	Rev	Reference
		27-03-2020	Ver1.0	


# **Activity Description**

Alarm Name	1. PLA_Down
Alarm Description	1. Physical Link Aggregation Down
Possible Causes	1. Link down in XPIC Link.



Prepared (also subject responsible if other)		No.			
Rajasekar R					
Approved	Checked	Date	Rev	Reference	
		27-03-2020	Ver1.0		

### **Flow Chart**





Prepared (also subject responsible if other)		No.		
Rajasekar R				
Approved	Checked	Date	Rev	Reference
		27-03-2020	Ver1.0	

### **Activity Details**

#### PLA Down:

PLA is used for balancing according to the idle bandwidth of each wireless link.

- 1. PLA will be done for XPIC links.
- 2. IF any one of the link is down, PLA Down will results.
- 3. Need to check and resolve the Link down issue.
- 4. Incase Slot changed to different slot Old configuration to be deleted.